

NAVAL POSTGRADUATE SCHOOL

Monterey, California



THESIS

PROCESSING, MICROSTRUCTURE AND
ELEVATED TEMPERATURE MECHANICAL
PROPERTIES OF A 6061 ALUMINUM -
ALUMINA METAL MATRIX COMPOSITE

by

Paul D. Macri

December 1990

Thesis Advisor
Co-Advisor

Terry R. McNelley
Peter N. Kalu

Approved for public release; distribution is unlimited.

Unclassified

security classification of this page

REPORT DOCUMENTATION PAGE

1a Report Security Classification Unclassified			1b Restrictive Markings		
2a Security Classification Authority			3 Distribution Availability of Report Further distribution only as directed by Superintendent, Code 043, Naval Postgraduate School, Monterey, CA 93943-5000, December 1990, or higher DoD authority.		
2b Declassification Downgrading Schedule					
4 Performing Organization Report Number(s)			5 Monitoring Organization Report Number(s)		
6a Name of Performing Organization Naval Postgraduate School		6b Office Symbol (if applicable) 34	7a Name of Monitoring Organization Naval Postgraduate School		
6c Address (city, state, and ZIP code) Monterey, CA 93943-5000			7b Address (city, state, and ZIP code) Monterey, CA 93943-5000		
8a Name of Funding Sponsoring Organization		8b Office Symbol (if applicable)	9 Procurement Instrument Identification Number		
8c Address (city, state, and ZIP code)			10 Source of Funding Numbers		
			Program Element No	Project No	Task No
			Work Unit Accession No		
11 Title (include security classification) PROCESSING, MICROSTRUCTURE AND ELEVATED TEMPERATURE MECHANICAL PROPERTIES OF A 6061 ALUMINUM - ALUMINA MATRIX COMPOSITE					
12 Personal Author(s) Paul D. Macri					
13a Type of Report Master's Thesis		13b Time Covered From To		14 Date of Report (year, month, day) December 1990	15 Page Count 108
16 Supplementary Notation The views expressed in this thesis are those of the author and do not reflect the official policy or position of the Department of Defense or the U.S. Government.					
17 Cosati Codes			18 Subject Terms (continue on reverse if necessary and identify by block number)		
Field	Group	Subgroup	Thermomechanical Processing 6061 Al		
19 Abstract (continue on reverse if necessary and identify by block number) A study was conducted on the effects of thermomechanical processing by warm rolling of a cast, aluminum-based discontinuous metal matrix composite. The material studied was a 6061 aluminum containing 10 or 15 volume percent alumina (Al_2O_3) particles. The material was cast and extruded by DURALCAN Inc. of San Diego, California. The subsequent processing included rolling at either 250°C or 350°C with reheating and annealing always at 350°C. The microstructure was studied by both optical and transmission electron microscopy. A significant improvement in the distribution of the Al_2O_3 particles was achieved by the thermomechanical processing. It is also shown that a substantial grain refinement (from a grain size of 500 μm to 20 μm) accompanied the improved particle distribution. The elevated temperature ductility and strength did not differ significantly with volume percent of Al_2O_3 added. Also, the details of the thermomechanical processing did not effect the strength at higher temperatures.					
20 Distribution Availability of Abstract <input checked="" type="checkbox"/> unclassified unlimited <input type="checkbox"/> same as report <input type="checkbox"/> DTIC users			21 Abstract Security Classification Unclassified		
22a Name of Responsible Individual Terry R. McNelley			22b Telephone (include Area code) (408) 646-2586	22c Office Symbol 69HY	

Further distribution only as directed by Superintendent, Code 043, Naval Postgraduate School, Monterey, CA 93943-5000, December 1990, or higher DoD authority.

Processing, Microstructure and
Elevated Temperature Mechanical
Properties of a 6061 Aluminum -
Alumina Metal Matrix Composite

by

Paul D. Macri
Lieutenant, United States Navy
B.S., Pennsylvania State University, 1983

Submitted in partial fulfillment of the
requirements for the degree of

MASTER OF SCIENCE IN MECHANICAL ENGINEERING

from the

NAVAL POSTGRADUATE SCHOOL
December 1990

ABSTRACT

A study was conducted on the effects of thermomechanical processing by warm rolling of a cast, aluminum-based discontinuous metal matrix composite. The material studied was a 6061 aluminum containing 10 or 15 volume percent alumina (Al_2O_3) particles. The material was cast and extruded by DURALCAN Inc. of San Diego, California. The subsequent processing included rolling at either 250°C or 350°C with reheating and annealing always at 350°C. The microstructure was studied by both optical and transmission electron microscopy. A significant improvement in the distribution of the Al_2O_3 particles was achieved by the thermomechanical processing. It is also shown that a substantial grain refinement (from a grain size of 500 μm to 20 μm) accompanied the improved particle distribution. The elevated temperature ductility and strength did not differ significantly with volume percent of Al_2O_3 added. Also, the details of the thermomechanical processing did not effect the strength at higher temperatures.

TABLE OF CONTENTS

I. INTRODUCTION	1
II. BACKGROUND	3
A. THE MATRIX ALLOY	3
B. THE REINFORCEMENT	4
C. THE COMPOSITE	6
D. POST CONSOLIDATION TREATMENT OF METAL MATRIX COM- POSITES	7
III. EXPERIMENTAL PROCEDURE	8
A. MATERIAL AND SECTIONING	8
B. THERMOMECHANICAL PROCESSING	8
C. MACHINING	12
D. TENSILE TESTING	12
E. DATA REDUCTION	13
F. OPTICAL MICROSCOPY	13
G. TRANSMISSION ELECTRON MICROSCOPY	14
H. DISTRIBUTION OF ALUMINA PARTICLES	14
IV. RESULTS AND DISCUSSION	16
A. AS EXTRUDED CONDITION	16
B. PROCESSED CONDITIONS	16
1. Effects of Processing on Microstructure	16
a. Size and Distribution of Particles	16
b. Recrystallization of the Matrix	17
2. Effects of Processing upon Mechanical Properties	28
a. The Temperature Dependence on Ductility	28
b. The Temperature Dependence of Ultimate Strength	29
C. SUMMARY	30
V. RECOMMENDATIONS FOR FURTHER STUDY	31

APPENDIX A. PROGRAMS	32
A. DATA ACQUISITION PROGRAM	32
1. Users Guide	32
2. Source Listing	33
B. DATA REDUCTION PROGRAM	52
1. Users Guide	52
2. Source Listing	52
APPENDIX B. TRUE STRESS VS. TRUE STRAIN CURVE	82
APPENDIX C. DUCTILITY VS. TEMPERATURE CURVES	83
APPENDIX D. ULTIMATE STRENGTH VS. TEMPERATURE CURVES ...	89
LIST OF REFERENCES	95
INITIAL DISTRIBUTION LIST	97

LIST OF TABLES

Table 1.	PROPERTIES OF UNREINFORCED ALUMINUM ALLOYS	3
Table 2.	REINFORCEMENT FOR LIQUID-METAL INFILTRATION	5
Table 3.	ROLLING SCHEDULE FOR TMP 1	9
Table 4.	MODIFIED ROLLING SCHEDULE FOR TMP 2	9
Table 5.	PROCESSING SCHEDULE FOR 6061 AL-ALUMINA 10 VOL. PCT.	10
Table 6.	PROCESSING SCHEDULE FOR 6061 AL-ALUMINA 15 VOL. PCT.	11
Table 7.	OPTICAL SAMPLE PREPARATION	14
Table 8.	MECHANICAL PROPERTIES FOLLOWING AGING TO PEAK STRENGTH	29

LIST OF FIGURES

Figure 1.	Extrusion of a metal	4
Figure 2.	Dimensions and tolerances for tensile test specimens.	12
Figure 3.	Self-aligning grip assembly for tensile test.	13
Figure 4.	Software display of distribution of	15
Figure 5.	Code system for specimen orientation [Ref.	16
Figure 6.	As-extruded top surface orientation of 10 vol. pct. Alumina (108X)	18
Figure 7.	Sample A after rolling pass one, 10 vol. pct. Alumina (54X).	18
Figure 8.	Sample C after rolling pass one, 15 vol. pct. Alumina (540X).	19
Figure 9.	Sample A after rolling pass six, 10 vol. pct. Alumina (54X).	19
Figure 10.	Sample C after rolling pass three, 15 vol. pct. Alumina (540X).	20
Figure 11.	Sample A after rolling pass nine, 10 vol. pct. Alumina (54X).	20
Figure 12.	Sample C after rolling pass six, 15 vol. pct. Alumina (540X).	21
Figure 13.	Sample C after rolling pass two, 15 vol. pct. Alumina (108X).	21
Figure 14.	Sample C after rolling pass five, 15 vol. pct. Alumina (108X).	22
Figure 15.	Sample C before rolling pass nine, 15 vol. pct. Alumina (54X).	22
Figure 16.	Sample C after rolling pass three, 15 vol. pct. Alumina (200X).	23
Figure 17.	Sample C after rolling pass eight, 15 vol. pct. Alumina (200X).	23
Figure 18.	Sample C after rolling pass three, 15 vol. pct. Alumina (200X).	24
Figure 19.	Sample F after rolling pass nine, 10 vol. pct. Alumina (200X).	25
Figure 20.	Sample G after rolling pass nine, 15 vol. pct. Alumina (200X).	26
Figure 21.	TEM micrograph, pinned grain boundary, 15 vol. pct. Alumina (80,000X)	26
Figure 22.	TEM micrograph, matrix fully recovered, 15 vol. pct. Alumina (80,000X)	27
Figure 23.	TEM micrograph showing high ρ , 15 vol. pct. Alumina (40,000X)	27
Figure 24.	Grain size vs. volume percent and particle diameter	28
Figure 25.	True stress vs. true strain, sample A, 10 vol. pct. Alumina, 400°C	83
Figure 26.	Ductility vs. temperature, sample A, 10 vol. pct. Alumina.	84
Figure 27.	Ductility vs. temperature, sample C, 15 vol. pct. Alumina.	85
Figure 28.	Ductility vs. temperature, sample F, 10 vol. pct. Alumina.	86
Figure 29.	Ductility vs. temperature, sample G, 15 vol. pct. Alumina.	87
Figure 30.	Ductility vs. temperature, sample F, 10 vol. pct. Alumina.	88
Figure 31.	Ductility vs. temperature, sample G, 15 vol. pct. Alumina.	89

Figure 32. Ultimate strength vs. temperature, sample A, 10 vol. pct. Alumina. . . . 89

Figure 33. Ultimate strength vs. temperature, sample C, 15 vol. pct. Alumina. . . . 90

Figure 34. Ultimate strength vs. temperature, sample F, 10 vol. pct. Alumina. . . . 91

Figure 35. Ultimate strength vs. temperature, sample G, 15 vol. pct. Alumina. . . . 92

Figure 36. Ultimate strength vs. temperature, sample F, 10 vol. pct. Alumina. . . . 93

Figure 37. Ultimate strength vs. temperature, sample G, 15 vol. pct. Alumina. . . . 94

ACKNOWLEDGMENTS

I would like to thank Professor Terry McNelley and Dr. Peter Kalu for their guidance and assistance through my research endeavor. I also wish to thank my parents, Paul and Roberta Macri, my father- and mother-in-law, Stanley and Arline Sobolewski, my wife Catherine, my son Scott and the Lord for the years of support and encouragement during my Naval career.

I. INTRODUCTION

In recent years there has been a growing scientific, industrial and military interest in the development of metal matrix composites (MMCs). MMCs offer an increase in modulus, tensile and compressive strengths greater than their unreinforced counterparts, improved friction and wear characteristics, reduced thermal expansion coefficients and other property combinations not obtainable in monolithic materials. A MMC offers an advantage over polymeric based composites in high temperature applications and also possesses improved stability with respect to vacuum and ultraviolet radiation [Ref. 1].

Composite materials are popular because one can design a new material to have a desired set of properties not found in any single existing material. The three categories of composites are: particulate; continuous fiber; and whisker reinforced composites. When using particles that are uniformly distributed, the composite will have isotropic properties, unlike the fiber- and whisker-containing materials. These particles may interact with dislocations or otherwise alter microstructure and thus cause an increase in strength [Ref. 2].

Cast ceramic-particle reinforced Aluminum alloy composites are available in production quantity. They can be shaped by conventional metal working processes such as extrusion, rolling and forging. Al 6061 with Alumina (Al_2O_3) is relatively easy to fabricate using casting methods. The wetting of the matrix material to particles is better with Al_2O_3 than with SiC. Adding large particles (3-50 μm) increases the modulus of elasticity. Also, there is no chemical reaction or need for adherent-corrosive protection of Al_2O_3 . However, the as-cast Al 6061 - Al_2O_3 material has poor ductility.

Dural Aluminum Composites Corporation (DURALCAN), based in San Diego, California, has developed a proprietary casting process. Their pretreatment process prevents the molten aluminum from chemically reacting with the particles while still ensuring adequate wetting. The pretreatment also reduces dissolved gases [Ref. 3]. DURALCAN produces castings of Al 6061 with 10 to 20 volume percent (vol. pct.) Al_2O_3 up to eleven inches in diameter. They produce shafts, bars, rectangles and tubes. Their production capacity will increase to 25 million pounds with the opening of a plant in Canada [Ref. 4]. With the high production capacity and excellent potential properties, there is a growing need for further research of MMC's.

This study is primarily microstructural in nature. The purpose of this thesis was to study the effect of the thermomechanical processing on the evolution of the microstructure and the development of mechanical properties in a 10 or 15 vol. pct. Al_2O_3 in 6061 Aluminum composite material.

II. BACKGROUND

A. THE MATRIX ALLOY

The matrix material is usually tough and ductile while the particulate addition is comparatively brittle. The matrix supports the particles, allows the load to be transmitted to the particles and prevents the cracks formed in particles from propagating through the entire structure. The matrix itself should be strong to contribute to the overall strength of the composite. Matrices of composites are either polymers, ceramics or metals. The polymeric composites are useful at relatively low temperatures. Ceramics are hard and brittle, but have good properties at very high temperatures. Most MMC's can operate at high temperatures, but production is more expensive than with a polymeric matrix. [Ref. 2]

Discontinuously reinforced Aluminum MMC's offer a higher stiffness per unit weight as compared to unreinforced alloys. Cast Aluminum MMC's have a large cost advantage over those processed via powder metallurgical methods. [Ref. 5] The subject of this research is a 6061 Aluminum alloy matrix. The 6XXX series (Al-Mg-Si alloys) is amenable to heat treatment in order to improve mechanical properties. The 6XXX series combines medium strength, good ductility, formability and weldability with minor property losses along with good corrosion resistance. See Table 1 [Ref. 6].

Table 1. PROPERTIES OF UNREINFORCED ALUMINUM ALLOYS

Alloy	Nominal Composition	Density g/cm ³	Elastic Modulus GPa	Yield Strength MPa	Ultimate Tensile Strength MPa	Failure Strain, Percent
2024 Al	4.4 Cu-1.5 Mg -0.6 Mn	2.77	72.4	414	483	13
5083 Al	4.5 Mg-0.35 Mn	2.66	69.3	234	317	12
6061 Al	1.0 Mg-0.28 Cu -0.2 Cr-0.6 Si	2.70	68.3	276	310	17
7075 Al	5.6 Zn-2.5 Mg -1.6 Cu-0.23 Cl	2.80	71.0	503	572	11

Al 6061 is typically tempered to a T4 or T6 condition. The T4 is solution heat treated and naturally aged to a substantially stable condition while the T6 is solution heat treated and then artificially aged [Ref. 7]. The 6061 alloy is often formed via extrusion. This hot working process is illustrated schematically in Figure 1 [Ref. 6]. Extrusion may involve area reductions as large as 25:1, corresponding to true strains of approximately 3.2 or more, in a single operation.




Figure 1. Extrusion of a metal

B. THE REINFORCEMENT

There are four types of materials that offer competition to discontinuous MMC's (DMMC). They are:

- Polymer based composites such as carbon fiber reinforced plastic (CFRP);
- Unreinforced, powder based metallic material (PM);
- Continuous fiber reinforced MMC's;
- Other cast or wrought metallic alloys.

The three types of DMMC reinforcements are short fibers ($3\mu\text{m}$ diameter, $\leq 50\mu\text{m}$ long), whiskers ($\leq 1\mu\text{m}$ diameter, $< 40\mu\text{m}$ long) and particles ($3\text{-}40\mu\text{m}$ diameter). This study involves the particulate type DMMC. DMMC's offer a smaller gain in mechanical properties, while still having isotropic behavior, as compared to continuous fiber com-

posites. In aluminum alloys it has been demonstrated that the following variables influence the microstructure of the alloy:

- the size and shape of the reinforcement;
- the volume fraction of the reinforcement;
- the processing route for the composite;
- the relative coefficient of expansion of reinforcement and matrix;
- the type of alloy. [Ref. 8]

The Al_2O_3 particles added are approximately 10 μm in diameter and irregularly shaped. The volume fractions were 0.10 and 0.15. The coefficients of expansion for Al_2O_3 and Aluminum are 6.7 and 25×10^{-6} $cm/cm^\circ C$, respectively, which is a factor of four difference [Ref. 2]. Table 2 shows the properties of various reinforcements for metal matrix composites [Ref. 9]. The properties of the various forms of reinforcement (particulate and fiber) can be compared.

Table 2. REINFORCEMENT FOR LIQUID-METAL INFILTRATION

	Strength (MPa)	Modulus (GPa)	Density (g/cm^3)	ϵ %	Diameter (μm)
Al_2O_3 (Saffil)	2000	300	3.3	0.67	3
Al_2O_3 (FP)	1380	379	3.9	0.36	20
Continuous SiC (Nicalon)	2760	200	2.55	1.5	10-15
SCS-2	3450	407	3.05	0.8	140
Carbon P-55	2068	380	2.25	0.5	10
P-75	2068	517	2.25	0.42	10
P-100	2240	690	2.25	0.5	10

C. THE COMPOSITE

There are at least five problems to be dealt with in casting a MMC material. These are:

- wetting
- dispersion
- inclusions
- porosity
- segregation.

Difficulty in wetting increases as the particle size decreases. This is due to the increased surface energy required as the particle penetrates through the liquid metal surface and thus finely divided powders tend to cluster together. Surface treatment of particles may be necessary to obtain particle wetting and thereby achieve an even distribution when composites are produced via the melt stirring route. Uniform dispersion is important for isotropy of properties. Inclusions, like oxide film on the surface, should be avoided. Aluminum will extract hydrogen from moisture in the environment. Hydrogen has a high solubility in liquid Aluminum. Inclusions in the melt provide nucleation sites for hydrogen bubbles which result in porosity. Dendritic segregation can cause clustering even though the particles may have been thoroughly dispersed in the melt. During freezing, a dendritic arm that encounters a second phase particle will either entrap it or push it aside. When freezing is complete, the particles pushed aside will be segregated into dendrite interstices [Ref. 10]. DURALCAN's pretreatment in their proprietary casting process prevents a chemical reaction between the particles and the matrix alloy while still ensuring adequate wetting, and reducing dissolved gases.

In the past, 6061 has had various applications in cars, trucks and marine superstructures. The Navy has an interest in developing the 6061 MMC for use in bulkhead doors and related applications. They would be light, stiff and have a high thermal conductivity. There are now possibilities that MMC's based on 6061 can have primary and secondary structural applications in the aerospace industry [Ref. 11]. MMC's have already been qualified for space flight as booms for the Space Telescope. There is also an interest in using MMC's on satellites as shields against pellet, nuclear or laser weapons [Ref. 12].

D. POST CONSOLIDATION TREATMENT OF METAL MATRIX COMPOSITES

The purpose of post-fabrication processing is to develop a homogeneous distribution of the particles throughout the matrix. DMMC's are sensitive to the distribution of the particles. The clustering of the particles causes a lowering of the strength and ductility of the composite. A common method, used for this material, is extrusion. However, other forms of treatment may involve forging or rolling.

It has been recognized that a single warm temperature deformation process coupled with prolonged annealing gives a different microstructure from a sequential deformation /anneal/deformation/anneal process as used in this study. Further refinement of an extruded composite can be accomplished using rolling. The rolling portion of the TMP involved nine warm-rolling passes with increasing strain per pass, and used two different annealing and rolling temperatures. The ambient properties of ductility and fracture toughness were the focus of work by Schaefer who examined the properties of this material in the as-extruded condition with subsequent TMP by warm rolling [Ref. 3]. The intent of the TMP was to improve the distribution of the Al_2O_3 in the matrix and to refine the grain size by the conclusion of processing. This thesis investigated elevated temperature testing of similarly processed materials.

III. EXPERIMENTAL PROCEDURE

A. MATERIAL AND SECTIONING

DURALCAN provided two samples of 6061 Aluminum with Al_2O_3 added. One contained 10 vol. pct. and the other 15 vol. pct. of Al_2O_3 . The MMC material was obtained in both the as-cast and as-extruded conditions.

The extruded rectangular bar had rounded corners and nominal dimensions 76 mm x 19 mm (3.0 in x 0.75 in). Two sections were cut using a power hack saw to dimensions of 38 mm x 66 mm x 19 mm (1.5 in x 2.6 in x 0.75 in) for use as rolling billets. [Ref. 3] An extra piece was processed with the first two and had smaller sections cut from it at intermediate stages of the rolling process in order to facilitate optical and transmission electron microscopy (TEM) for microstructural analysis.

B. THERMOMECHANICAL PROCESSING

In previous work by Schaefer [Ref. 3] and Magill [Ref. 13] it was recommended that TMP be conducted using a rolling temperature of 250°C, with annealing between passes at this same temperature. This was based on the observation of increased ductility during elevated temperature testing following a reduction in the rolling temperature from 500°C to 350°C [Ref. 13].

Billets for processing were always solutionized at 560°C for 90 minutes in a Lindberg type B-6 Heavy Duty Furnace to ensure homogeneity of the matrix. The billets were then water quenched to room temperature. The subsequent processing trials are described below.

Initial attempts to roll at 250°C were unsuccessful as the billets split at their mid-plane (alligatoring). A second series of processes were then conducted utilizing a rolling temperature of 250°C but with annealing at 350°C for varying lengths of time. It became apparent as well that the rolling schedule required modification to reduce the strain per pass in the early stages of rolling.

The rolling schedule used in most of the work is designated TMP 1 and is summarized in Table 3. A modified version is summarized in Table 4. The results of the rolling trials are summarized in Table 5 for the Al-6061 10 vol. pct. Al_2O_3 material in Table 6 for the Al-6061 15 vol. pct. Al_2O_3 material. Essentially, four of the seven combinations of Al_2O_3 content and TMP (designated subsequently as samples A, C, F and G) provided material for the remainder of this research.

Table 3. ROLLING SCHEDULE FOR TMP 1

ROLL #	ROLL CHANGE (0.08in + 0.01in)	MILL SETTING (left/right)	MILL GAP (in)	SILICONE LUBRICANT
1	+(8 + 0)	4/4	0.64	NO
2	-(1 + 2)	2/2	0.54	NO
3	-(1 + 2)	0/0	0.44	NO
4	-(1 + 2)	6/6	0.34	NO
5	-(1 + 2)	4/4	0.24	YES
6	-(0 + 6)	6/6	0.18	YES
7	-(0 + 6)	0/0	0.12	YES
8	-(0 + 5)	3/3	0.07	YES
9	-(0 + 2.2)	0.8/0.8	0.048	YES

Table 4. MODIFIED ROLLING SCHEDULE FOR TMP 2

ROLL #	ROLL CHANGE (0.08in + 0.01in)	MILL SETTING (left/right)	MILL GAP (in)	% STRAIN (per pass)
1	+(8 + 5)	1/1	0.72	4.0
2	-(1 + 0)	1/1	0.64	11.1
3	-(1 + 2)	7/7	0.54	15.5
4	-(1 + 2)	6/6	0.44	18.5
5	-(1 + 1)	5/5	0.35	21.5
6	-(1 + 1)	4/4	0.26	25.7
7	-(0 + 7)	7/7	0.19	26.9
8	-(0 + 6)	1/1	0.13	31.6
9	-(0 + 5)	4/4	0.08	38.5
10	-(0 + 3.2)	0.8/0.8	0.048	40.0

Table 5. PROCESSING SCHEDULE FOR 6061 AL-ALUMINA 10 VOL. PCT.

Roll and Anneal Temps	10% Vol		
	Size of Billet	Strain per roll	Comments
Sample A Anneal @ 350°C (30 min) Roll @ 250°C (5 min) (TMP 1)	0.75" x 1.5" X 2.6" (l/w \approx 1.6)	1 14.7	Partial split @ 2nd,3rd, and 4th rolls no further splitting
		2 15.6	
		3 18.6	
		4 22.7	
		5 29.4	
		6 25.0	
		7 50.0	
		8 41.7	
		9 31.4	
Sample B Roll/Anneal @ 250°C (30 min) (TMP 1)	0.75" x 1.5" X 2.6" (l/w \approx 1.6)	1 14.7	"alligator" Complete split after 2nd roll no further assesment of material
		2 15.6	
		3 18.6	
		4 22.7	
		5 29.4	
		6 25.0	
		7 50.0	
		8 41.7	
		9 31.4	
Sample D Roll/Anneal @ 250°C (30 min) (TMP 2)	0.75" x 1.4" X 5.7" (l/w \approx 4.0)	1 4.0	"alligator" Complete split after 2nd roll no further assesment of material
		2 11.1	
		3 15.5	
		4 18.5	
		5 21.5	
		6 25.7	
		7 26.9	
		8 31.6	
		9 38.5	
Sample F Roll/Anneal @ 350°C (60 min) (TMP 1)	0.75" x 1.4" X 5.7" (l/w \approx 4.0)	1 14.7	No splitting
		2 15.6	
		3 18.6	
		4 22.7	
		5 29.4	
		6 25.0	
		7 50.0	
		8 41.7	
		9 31.4	

Table 6. PROCESSING SCHEDULE FOR 6061 AL-ALUMINA 15 VOL. PCT.

Roll and Anneal Temps	15% Vol		
	Size of Billet	Strain per roll	Comments
Sample C Anneal @ 350°C (30 min) Roll @ 250°C (5 min) (TMP 1)	0.75" x 1.4" X 5.5" (l/w \approx 4.0)	1 14.7 2 15.6 3 18.6 4 22.7 5 29.4 6 25.0 7 50.0 8 41.7 9 31.4	No splitting
Sample E Roll/Anneal @ 250°C (30 min) (TMP 2)	0.75" x 1.4" X 5.7" (l/w \approx 4.0)	1 4.0 2 11.1 3 15.5 4 18.5 5 21.5 6 25.7 7 26.9 8 31.6 9 38.5 10 40.0	"alligator" Complete split after 3rd roll no further assesment of material
Sample G Roll/Anneal @ 250°C (60 min) (TMP 1)	0.75" x 1.4" X 5.7" (l/w \approx 4.0)	1 14.7 2 15.6 3 18.6 4 22.7 5 29.4 6 25.0 7 50.0 8 41.7 9 31.4	Partial split @ 3rd roll no further splitting

C. MACHINING

A diamond-tipped cutting tool reduced the amount of tool wear while cutting the harder 15 vol. pct. samples. The tension test coupons were machined to the specifications given in Figure 2.




Figure 2. Dimensions and tolerances for tensile test specimens.

D. TENSILE TESTING

The tensile load cell output of an Instron Model 6027 test machine was fed into a Hewlett Packard Model 3852A Data Acquisition Unit which produced load vs. time graphs. The tests were performed at 350°C using a Marshall Model 1137 Furnace rated to 1100°C and controlled by a Eurotherm Model 199 temperature controller. There were five thermocouples used to monitor the temperature of the test sample. One was at the center of the coupon while the other two pairs were one-half inches above and below the centerline of the sample. The crosshead speed was maintained at either of two different strain rates, corresponding to 5.08 or 50.8 mm/min. The nominal strain rates were $6.7 \times 10^{-3} \text{s}^{-1}$ and $6.7 \times 10^{-2} \text{s}^{-1}$, respectively. Self-aligning grips were used to hold the tensile test specimens as in Figure 3 [Ref. 14].




Figure 3. Self-aligning grip assembly for tensile test.

E. DATA REDUCTION

Programs were developed for the HHP-9000 computer for data analysis. Load vs. time data was collected during the tensile testing. To correct for grip slippage, the slope of the elastic region of the load vs. time graph was calculated. The horizontal displacement from the elastic line on the load-time graph was used to determine and plot the engineering stress vs. engineering plastic strain. The software is in the developmental stages and the program codes for data acquisition and data reduction are enclosed in Appendix A.

F. OPTICAL MICROSCOPY

The samples were mounted in Buehler Sampl-Kwick thermoset plastic. The samples were cleaned with detergent, rinsed and dried between steps. Plastic gloves were worn when using the OPS colloidal silica due to its caustic nature. For steps four through six on Table 7, Plan, Mol and OP Chem papers, respectively, were used on the polishing wheels. These papers yielded a significant improvement in the quality of the prepared samples.

Table 7. OPTICAL SAMPLE PREPARATION

STEP #	POLISHING MEDIUM	LOAD, RPM	LUBRICANT	TIME
1	240 GRIT	light/ -	water	2 min
2	400 GRIT	light/ -	water	2 min
3	600 GRIT	light/ -	water	2 min
4	6 μm diamond paste (Metadi)	light/ 150	DP Lubricant Red (Struers)	3 min
5	3 μm diamond paste (Metadi)	light/ 150	DP Lubricant Red (Struers)	2 min
6	colloid silica	light/ 150	Beulers Mastemet	2 min

Once the micrographs were obtained to reveal the distribution of the Al_2O_3 reinforcement, the optical-microscopy samples were anodized to examine the microstructure of the matrix. The etchant was a modified Barker's reagent (HBF_4 (48% solution), 46 cm^3 ; boric acid, 79 cm^3 ; H_2O , 970 cm^3) [Ref. 15].

G. TRANSMISSION ELECTRON MICROSCOPY

The material sectioned after each rolling pass was saved for optical and Transmission Electron Microscope (TEM) work. The TEM samples were 3.0 mm disks, 0.2 mm thick, and cut by a Metals Research, Ltd., S.M.D. Servomet Mark Machine. The samples were mechanically polished down to a thickness of about 25 μm and dimpled to about 26 μm on a Gatan dimple grinder, Model 656. The samples were finally thinned in a Gatan Dual Beam Ion Mill Model 600 at an accelerating voltage of 6 KV and a gain current of about 100 microamps.

H. DISTRIBUTION OF ALUMINA PARTICLES

A video camera was attached to the eye piece of an Zeiss ICM 405 optical microscope. The field of view of the sample at a magnification of 540X was displayed on a Sony model PVM-1343MD color video monitor. The MicroScience *ImageMeasure*® version 4.02 software package was used to determine the volume percentage of the Al_2O_3 . Each pixel was assigned a shade value from 0 to 255, with black being zero, white, 255, and the shades of grey ranged from 1 to 254. The matrix (Al) ranged from 0-70 and the particles (Al_2O_3) had shades of grey of approximately 62 at the edges to about 92 at

the center. The contrast bias was used to cancel all lighter shades from 92 to 255. This allowed only the particles themselves to be depicted on the screen with a totally white background. This allowed the program to determine the particles as a percentage of the total field of view. A hard copy of the screen is illustrated in Figure 4 which shows an actual particle percentage of 15.7% for the 15 vol. pct. sample.




Figure 4. Software display of distribution of Al_2O_3

IV. RESULTS AND DISCUSSION

A. AS EXTRUDED CONDITION

The extruded bar was sectioned to examine the transverse, top and longitudinal surfaces as shown in Figure 5 [Ref. 16]. The top surface was examined in the as-extruded sample by optical microscopy and samples were prepared subsequently after each rolling pass. Figure 6 shows the clustering of particles with some banding. On this scale it is not readily apparent that the particles are not randomly distributed. The arrows show examples of where particles are clustered together next to an area lacking particles.




Figure 5. Code system for specimen orientation [Ref. 16].

B. PROCESSED CONDITIONS

1. Effects of Processing on Microstructure

a. Size and Distribution of Particles

The development of the microstructure was characterized at three different stages: the initial stage (rolling passes one to three), the intermediate stage (rolling passes four to seven), and the final stage (rolling passes eight and nine). All the following micrographs show the results for material processed by TMP 1. After the first rolling pass on sample A (10 vol. pct. Al_2O_3), the particle distribution can be seen in Figure 7. There is clustering of particles with areas that are apparently devoid of particles. Less

banding is apparent when compared to the extruded condition. In the initial rolling passes, there is an increase in strain in each succeeding pass of the TMP and the particle clusters are being dispersed. However, while the clusters are being broken up, the particles themselves remain intact. At higher magnifications, the extent of the clustering is more evident. Figure 8 shows the clustering of particles after the first rolling pass. At this magnification (540 X) the tight grouping of the particles is clearly seen with other areas having few particles. During the intermediate stage, as can be seen in Figure 9, clusters are "smeared" into a banded structure. Figure 10 shows that the clusters themselves are being broken up to some extent. After the ninth pass, a fairly random distribution of the particles have been achieved as shown in Figure 11 and Figure 12.

A similar development through the rolling can be seen in sample C (15 vol. pct. Al_2O_3). Figure 13 shows the structure after rolling pass two. In Figure 14, after rolling pass five, the banding in the structure is more apparent. Figure 15 is just prior to rolling pass nine. There are still remnants of the banding but the tight clusters from the extruded condition are gone. Indeed, looking at rolling pass one and comparing to rolling pass nine there is a subtle change in the particle distribution.

The particle size remains the same throughout. The particles are not fractured into finer pieces. The distribution of particles changes from a random distribution of clusters to a banded structure, and finally to a more evenly dispersed, less banded structure.

b. Recrystallization of the Matrix

It is evident from Figure 16 and Figure 17 that substantial grain refinement has resulted as well from the TMP. Compare the grain size of about 500 μm after the third rolling pass on sample C (15 vol. pct. Al_2O_3) to about 20 μm after rolling pass eight. This sample was annealed as well for 30 mins at 350°C after pass number eight. The microstructure at the early stages of processing (see Figure 16) is not well defined except at the neighborhood of the particles where the localized contrast suggests the formation of local lattice rotation. These highly deformed sites in turn help to promote particle-stimulated nucleation during annealing, as shown in Figure 18. It is highly probable that this mechanism is the key to the grain refinement. Further evidence to confirm the




Figure 6. As-extruded top surface orientation of 10 vol. pct. Alumina (108X)




Figure 7. Sample A after rolling pass one, 10 vol. pct. Alumina (54X).




Figure 8. Sample C after rolling pass one, 15 vol. pct. Alumina (540X).




Figure 9. Sample A after rolling pass six, 10 vol. pct. Alumina (54X).




Figure 10. Sample C after rolling pass three, 15 vol. pct. Alumina (540X).




Figure 11. Sample A after rolling pass nine, 10 vol. pct. Alumina (54X).




Figure 12. Sample C after rolling pass six, 15 vol. pct. Alumina (540X).




Figure 13. Sample C after rolling pass two, 15 vol. pct. Alumina (108X).




Figure 14. Sample C after rolling pass five, 15 vol. pct. Alumina (108X).




Figure 15. Sample C before rolling pass nine, 15 vol. pct. Alumina (54X).




Figure 16. Sample C after rolling pass three, 15 vol. pct. Alumina (200X).




Figure 17. Sample C after rolling pass eight, 15 vol. pct. Alumina (200X).



Figure 18. Sample C after rolling pass three, 15 vol. pct. Alumina (200X).

mechanism of particle-stimulated nucleation can be seen in the TEM micrograph (Figure 23) which shows extensive dislocation entanglement at the vicinity of a particle. A high dislocation density can be observed next to a large Al_2O_3 particle. This would provide the driving force for the particle-stimulated recrystallization.

The extent of recrystallization is still greater after rolling pass nine of sample F (10 vol. pct. Al_2O_3) and G (15 vol. pct. Al_2O_3) as seen in Figure 19 and Figure 20, respectively. Both of these had one hour of annealing between rolling passes. Comparing among Figure 19, Figure 20, and Figure 17, reveals that the structure is very similar in the 10 vol. pct. and 15 vol. pct. cases.

The TEM micrograph of sample C, Figure 21, shows a fine particle pinning the grain boundary. In the matrix region the dislocation density is relatively very low. It is similar to a fully recovered structure. The TEM micrograph of sample C in Figure 22 shows the fully recovered matrix with fine precipitates also present. The only notable difference is the precipitation of Mg_2Si that appears to be coarser with the longer reheating interval, (one hour for F and G versus one-half hour for C). Thus, increasing the reheating interval for either the 10 or 15 vol. pct. of material does not alter significantly the extent of microstructure refinement, but just coarsens the precipitates of the Mg_2Si phase.

The structure uniformly recrystallizes with a grain size that corresponds to the interparticle spacing. It has been suggested that the recrystallized grain size can be predicted based on volume percent and particle size. From Figure 24 it can be seen that for a $10\text{ }\mu\text{m}$ particle diameter we would expect a grain size of approximately $20\text{ }\mu\text{m}$ for 10 vol. pct. composite and a smaller grain size of about $17\text{ }\mu\text{m}$ for the 15 vol. pct. case [Ref. 17]. It is interesting to note that our result compares well with this prediction. In Figure 19 and Figure 20, we see a smaller grain size: for the higher volume percent. The higher the volume percent of the particles, the lower the interparticle spacing and the finer the resulting grain. The more homogeneous the particle distribution, the more uniform the grain size. Both of these factors, then, contribute to a fine, uniform microstructure. The matrix starts out with fairly large grains which are refined and recrystallized by the end of the TMP.




Figure 19. Sample F after rolling pass nine, 10 vol. pct. Alumina (200X).




Figure 20. Sample G after rolling pass nine, 15 vol. pct. Alumina (200X).




Figure 21. TEM micrograph, pinned grain boundary, 15 vol. pct. Alumina (80,000X)



Figure 22. TEM micrograph, matrix fully recovered, 15 vol. pct. Alumina (80,000X)




Figure 23. TEM micrograph showing high ρ , 15 vol. pct. Alumina (40,000X)




Figure 24. Grain size vs. volume percent and particle diameter [ref. 1]

2. Effects of Processing upon Mechanical Properties

a. The Temperature Dependence on Ductility

The as-cast material is extremely brittle. The as-extruded material has a ductility of about 10-15 percent elongation to fracture in the temperature interval of interest. A typical stress-strain curve from the current investigation is shown in Appendix B, and the ductility averaged between 20-60 percent elongation on this condition for the composite.

The ductility-temperature response does not vary significantly with the change in volume percentage of Al_2O_3 . The ductility peaks at approximately 375°C for the 10 vol. pct. Al_2O_3 material (see Figure 26 in Appendix C). The corresponding temperature for the 15 vol. pct. sample was 425°C (see Figure 27). For samples F and G, which were annealed for one hour versus one-half hour for samples A and C (see

Figure 28 and Figure 29), the ductilities and peak temperature were comparable. A comparison of the previous work using one-half hour anneal and the current work done using one-hour of annealing is shown in Figure 30 and Figure 31 [ref. 13]. The ductility was found to be less than in the previous research. The previous data show a slightly higher tensile ductility when higher rolling temperatures are used. The ductility data for the current study are summarized in Appendix C. It is evident from these results that the TMP yields in an enhanced ductility when compared with the ductility of the as-extruded condition.

b. The Temperature Dependence of Ultimate Strength

The ambient temperature properties of this material is shown in Table 8 [Ref. 3]. It is noteworthy that both the ambient strength and ductility are improved by the processing.

The UTS decreases with increasing temperature as shown in Figure 32, Figure 33, Figure 34, and Figure 35 in Appendix D. As with the ductility, the ultimate strength (UTS) does not change significantly with the volume percentage of Al_2O_3 . Comparing to data from previous work, different annealing time does not effect the UTS at higher test temperatures [Ref. 13]. Previous data showed an increase in strength at higher rolling temperatures (see Figure 36 and Figure 37). At lower rolling temperatures the specimens proved to be weaker at the lower tensile test temperatures.

Table 8. MECHANICAL PROPERTIES FOLLOWING AGING TO PEAK STRENGTH

Material Condition	Yield Strength (MPa)	Ultimate Tensile Strength (MPa)	Percent Elongation (%)
6061-T6 Unreinforced	276	310	12
Extruded	328	350	5.6
350°C Rolled	375	374	7.0

There are two general observations on the mechanical data:

1. Reduced pass temperature yields a material weaker at low test temperatures but without any enhancement in ductility.
2. Decreasing the anneal time between rolling passes increases the strength, and significantly enhances the ductility. Thirty minutes appears to be the optimum time.

C. SUMMARY

This investigation was a study of the effects of TMP on the evolution of the microstructure in an aluminum MMC containing either 10 or 15 vol. pct. Al_2O_3 . The as-cast material is extremely brittle due to the non-homogeneous particle distribution in the matrix. When extruded at a 17 to 1 ratio, the particle distribution improved which resulted in higher strengths and ductilities. Thermomechanical processing by isothermal rolling at 250°C and 350°C further improved the particle distribution.

This study has followed the development of the microstructure from the beginning to the end of a rolling sequence. The processing did homogenize the microstructure. The particle distribution was improved without any sign of particle fracture. The matrix was recrystallized by the TMP and the matrix grains were refined from 500 to 20 μm . The mechanical properties were greatly improved when compared to the as-cast or extruded material. A longer anneal time between rolling passes seems to indicate a coarser microstructure with more time for grain growth and the precipitation of the Mg_2Si phase. The mechanical properties were enhanced in the ambient and elevated temperature tests [Ref. 3]. The lower pass temperature yielded a material weaker at low test temperatures without any enhancement in ductility. Decreasing the anneal time between rolling passes slightly increases the strength and significantly enhanced the ductility.

V. RECOMMENDATIONS FOR FURTHER STUDY

1. Perform identical experimentation on a monolith 6061 and compare to the MMC results.
2. Use TMP 2 (with the increasing strain per pass) and examine the microstructure and mechanical data as compared to TMP 1.
3. Attempt TMP 2 at 350°C for both rolling and annealing until approximately the fifth rolling pass and then use only 250°C for the rest of the process. This should prevent the alligator cracks early in the processing.
4. Increase the width to thickness ratio and decrease the length to width ratio to 3.0 to prevent "alligator" cracking. This will allow for the partially split material to be sectioned off and used for optical examination while still having ample material remaining to continue the TMP and machine a sufficient quantity of coupons.
5. Investigate the properties with an anneal time between rolling passes of approximately twenty minutes.
6. Investigate the properties of still higher volume fraction MMC.

APPENDIX A. PROGRAMS

A. DATA ACQUISITION PROGRAM

Due to the limitations of the Instron 6027 plotter, a program was written for the Hewlett Packard 3852A Data Acquisition System (HP) to acquire the load data from the Instron [Ref. 18]. This program was subsequently broken into two sub-programs with redundant sections removed and extra features added. This solved the problem of one program having inadequate memory to do all that was required. The first program called ACQR and the second is called REDUCE.

1. Users Guide

ACQR performs several functions. It will acquire the voltage signals from the Instron 6027 while plotting that load vs. time data simultaneously. The data can be graphed on the video screen or on the hard copy plotter. The data can then be stored on either the 3 1/2" floppy or hard disks.

Once the HP system is powered up, it will ask if you wish to use the floppy or hard disk drive to load the program. Choosing the hard drive will give the menu for the installed programs. Select item 7 for 'OTHER'. The next menu choice will be 'ACQR'. The program then asks if you wish to see the operating instructions which are summarized below. The instructions show:

1. Sample data
 - a. Sample geometry and dimensions
 - b. Identify sample
 - c. Test temperature
 - d. Cross head speed
 - e. Load cell range
 - f. Tension or compression test
 - g. Plotting parameters
2. Running a Test
 - a. Choose to view the data collection while in progress on the screen or plotter
 - b. Start the test once the Instron is engaged
 - c. Test complete
3. Save and Verify Data

- a. Store data - the program looks at the number of data points and allocates a sector on the disk with the exact size of memory required. The program tells you the name of the last program saved as a reminder. You are filing the data in two stages. You are giving the name that the file will have and you allocate the amount of memory space needed to accomodate the file. The (empty) file is created in the correct size required. The second stage is the filing of the data into the empty file which had just been created in the name you have chosen.
- b. Verify data - once filed, use 'RECALL OLD DATA' using the same name (the program will remind you what the last file was). If the recording was succesful you can replot the raw data or use the REDUCE program later.

The program will list the current files in the drive that is in use. It will notify the user if the disk in use is full and that another must be used to save the intended data. The data can be stored in the voltage signals or converted into load data and filed.

2. Source Listing

```

10  ! Program to acquire data by the HP 3852A from the Instron 6027
15  ! Written 03-10-88 Tom Kelloo as INST 6027
20  ! Revised 09OCT90 by Paul Macri
25  ! Stored as ACQR
30  DIM Strain(5000),Strass(5000),Sample nr$(50),Area i(5000),Extens(5000)
35  ! note: Extens is used for inputting strain gage data
40  DIM X axis$(25)
41  File name$="NONE YET"
42  Starter: 1
43  PRINTER IS 1
45  KEY LABELS OFF
46  CLEAR SCREEN
47  PRINT " "
48  PRINT " "
50  PRINT "          Do you want operating instructions?"
51  GOSUB Yes no
52  IF Answer$="N" THEN GOTO Init sec
53  OFF KEY
54  ON KEY 1 LABEL " Sample Data " GOTO Page 1
55  ON KEY 2 LABEL "Running a Test " GOTO Page 2
56  ON KEY 3 LABEL " Verify Data " GOTO Page 3
57  ON KEY 4 LABEL "          " GOTO Ms spin
58  ON KEY 5 LABEL "          " GOTO Ms spin
59  ON KEY 6 LABEL "CONTINUE " GOTO Init sec
60  ON KEY 7 LABEL " QUIT" GOTO Stopper
61  ON KEY 8 LABEL " MAIN MENU " GOTO Main menu
62  KEY LABELS ON
63  Ms spin: GOTO Ms spin
64  Page 1: !
65  CLEAR SCREEN

```

```

66 PRINT " OPERATING INSTRUCTIONS FOR DATA ACQUISITION"
67 PRINT " "
68 PRINT "I. Change Current Set-up"
69 PRINT " 1. <NEED SAMPLE DIMENSIONS>"
70 PRINT " - sample geometry and dimensions <RECT> & type numbers <
RETURN>"
71 PRINT " 2. <IDENTIFY SAMPLE> - describe sample"
72 PRINT " 3. <CHANGE SET-UP>"
73 PRINT " A. <SAMPLE PARAMETERS>"
74 PRINT " - <CHANGE TEMP> type heater tem
p"
75 PRINT " B. <TEST PARAMETERS>"
76 PRINT " - <CHANGE CROSS HEAD SPEED>"
77 PRINT " - <CHANGE LOADING CELL RANGE>"
78 PRINT " - <TENSION/COMPRESSION>"
79 PRINT " C. <PLOTting PARAMETERS>"
80 PRINT " - X,Y axes labels; X,Y minimum and maximum values"
81 PRINT " 4. <SHOW SET-UP> - change mistakes if any"
82 PRINT " 5. <SET-UP OK>"
83 PRINT " "
84 PRINT " SEE 'Running a test' FOR THE INFORMATION NEEDED NEXT"
85 GOTO Ms spin
86 Page 2: !
87 CLEAR SCREEN
89 PRINT " HOW TO START A TEST RUN"
90 PRINT " "
91 PRINT "II. <RUN>"
92 PRINT " - use plotter? <YES>"
93 PRINT " - load paper <RETURN>"
94 PRINT " - choose pen draws axes"
95 PRINT " ensure INSTRON printer is 'ONLINE' or there's NO DATA COMING"
97 PRINT " when INSTRON started and ready to acquire data <RETURN>"
98 PRINT " when INSTRON finished and test complete <TEST COMPLETE>"
99 PRINT " 1. <MAIN MENU>"
100 PRINT " 2. <STORE DATA>"
101 PRINT " - Do you want to store data to the floppy disk? <YES>"
102 PRINT " - file to be used? give it a name"
103 PRINT " - create a new file? <YES>"
104 PRINT " - Do you want to store data? <YES>"
105 PRINT " "
106 PRINT " "
107 PRINT " "
108 PRINT " SEE 'Verify data' FOR THE INFORMATION NEEDED NEXT"
109 GOTO Ms spin
110 Page 3: !
111 CLEAR SCREEN
112 PRINT " HOW TO VERIFY THE DATA WAS STORED ON THE FLOPPY DISK"
113 PRINT " "
114 PRINT "III. <RECALL OLD DATA>"
115 PRINT " - recall data from floppy? <YES>"
116 PRINT " - file last used was: "

```

```

117 PRINT "      - file to be used?                  same name as abo
ve"
118 PRINT "      - Do you want to use plotter?          <NO>"
119 PRINT "      - <MAIN MENU>"
120 PRINT "      - <SHOW SET-UP>              verify"
121 PRINT "      - <PLOT DATA>
122 PRINT "      - <CHANGE MAIN AXES>          if needed"
123 PRINT "      - create a new file?              <YES>"
124 PRINT "      - Do you want to use plotter?          <YES>"
125 PRINT "      - <CONTINUE PLOT>      "
126 PRINT "      - <PRINT DATA>                  gives hard copy of set
-up"
127 PRINT "      "
128 PRINT "      "
129 PRINT " END OF INSTRUCTIONS          PRESS <CONTINUE>"
130 GOTO Ms_spin
131 Init_sec: !
132 Str_rate=1.07 !mm/min
133 Gauge=12.7 !gauge length in mm
134 T_start=0
135 T_end=1000
136 T_total=1000
137 Load_min=0
138 Load_max=2
139 Fs_load_cell=20
140 Test_temp=300
141 X_axis$="Time, minutes"
142 Y_axis$="Load, kN"
143 Te_co=1 !TENSION ONLY TEST
144 Extensometer$="Off"
145 Ex_convert=1
146 Ex_inter=0
147 Exp_con=1
148 Exp_int=0
149 ExpLOT=0
150 ExpLOTmax=20
151 Wide=0
152 Thick=0
153 GOSUB Show_set_up
154 Main_menu: !
155 BEEP 2000..1
156 OFF KEY
157 ON KEY 1 LABEL "Change Set-up" GOTO Set_up_menu
158 ON KEY 2 LABEL "Show Set-up" GOTO Show_set_up_d
159 ON KEY 3 LABEL "QUIT" GOTO Stopper
160 ON KEY 4 LABEL "QUIT" GOTO Stopper
161 ON KEY 5 LABEL "Store Data" GOTO Store_data
162 ON KEY 6 LABEL "Plot Data" GOTO Plot_data
163 ON KEY 7 LABEL "Recall Old Data" GOTO Recall_data
164 ON KEY 8 LABEL "RUN" GOTO Set_up_ok
165 IF (Y_axis$="Load, kN" OR Y_axis$="Stress, MPa") AND Fs_load_cell=0 THEN

```

```

167     ON KEY 7 LABEL "NEED    LOADCELL" GOTO Load_cell
168     ON KEY 8 LABEL "DATA    NEEDED" GOTO Main_menu
169     BEEP 2000..1
170     BEEP 2500..1
171     ENO IF
172     IF (Sample_area=0 OR Gauge=0) THEN
173         ON KEY 3 LABEL "NEED SA.DIMEN." GOTO S_area_1
174         ON KEY 8 LABEL "DATA    NEEDED" GOTO Main_menu
175         BEEP 2000..1
176         BEEP 2500..1
177     END IF
178     IF Sample_nrs="" THEN
179         ON KEY 4 LABEL "IDENTIFYSAMPLE" TO Sample_id_m
180         ON KEY 8 LABEL "DATA    NEEDED" TO Main_menu
181         BEEP 2000..1
182         BEEP 2500..1
183     END IF
184     KEY LABELS ON
185     Main_menu_idle:GOTO Main_menu_idle
186     Sample_id_s: !
187     ON KEY 1 LABEL "IdentifySample" GOTO Sample_id_s_2
188     ON KEY 2 LABEL "IdentifySample" GOTO Sample_id_s_2
189     ON KEY 3 LABEL "Change Temp" GOTO Chq_test_temp
190     ON KEY 4 LABEL "Change Temp" GOTO Chq_test_temp
191     FOR Q=5 TO 8
192         ON KEY Q LABEL "Change Oimen's" GOTO S_area_2
193     NEXT Q
194     Sample_id_spin:GOTO Sample_id_spin
195     Chq_test_temp: !
196     Var=Test_temp
197     GOSUB Var_change
198     Test_temp=Var
199     GOTO Set_up_menu
200     Sample_id_s_2: !
201     GOSUB Sample_id
202     GOTO Set_up_menu
203     Sample_id_m: !
204     GOSUB Sample_id
205     GOTO Main_menu
206     Sample_id: !
207     KEY LABELS OFF
208     INPUT "Identify sample 50 characters max",Sample_nrs
209     RETURN
210     S_area_1: !
211     GOSUB S_area
212     GOTO Main_menu
213     S_area_2: !
214     GOSUB S_area
215     GOTO Set_up_menu
216     Show_set_up_q: !
217     GOSUB Show_set_up

```



```

218 GOTO Main_menu
219 Recall_data: I
220 GOSUB Re_data
221 GOTO Plot_data
222 Re_data: I
223 GOSUB Which_msu
224 ON ERROR GOTO Input_err
225 INPUT "File to be used? Don't type suffix X,Y,Z or Q.",File_name$
226 Xfile$=File_name$&"8"
227 Yfile$=File_name$&"C"
228 Zfile$=File_name$&"Z"
229 Qfile$=File_name$&"Q"
230 ASSIGN @Path1 TO Xfile$
231 ASSIGN @Path2 TO Yfile$
232 ASSIGN @Path3 TO Zfile$
233 ASSIGN @Path4 TO Qfile$
234 N_points=5000!THIS IS TO RESET FROM LAST N_points SO ALL DATA IS PLOTTEO
236 I ON ENO @Path3 GOTO Plot_data
237 OFF ERROR
238 ON ERROR GOTO 240
239 ENTER @Path1;Strain(*)
240 OFF ERROR
241 ON ERROR GOTO 243
242 ENTER @Path2;Stress(*)
243 OFF ERROR
244 ON ERROR GOTO 248
245 E_c=Ex_convert
246 E_i=Ex_inter
247 ENTER @Path3;Sample_nr$,X_axis$,Y_axis$,Dia,Wide,Thick,Gauge,T_start,T_end
,Load_min,Load_max,Fs_load_cell,Te_co,Str_rate,Extensometer$,E_c,E_i,Test_temp
248 OFF ERROR
249 ON ERROR GOTO 252
250 ENTER @Path4;Extens(*)
251 OFF ERROR
252 ASSIGN @Path4 TO *
253 ASSIGN @Path1 TO *
254 ASSIGN @Path2 TO *
255 ASSIGN @Path3 TO *
256 RETURN
257 Input_err: I
258 PRINTER IS I
259 IF ERRN=56 THEN
260 PRINTER IS 701
261 CAT
262 FOR Q=1 TO 5
263 PRINT
264 NEXT Q
265 PRINTER IS I
266 END IF
267 PRINT USING "@,#"

```

```

268 BEEP
269 PRINT ERRM$
270 GOTO Recall_data
271 Store_data: !
272 GOSUB Which_msu
273 ON ERROR GOTO Store_err
274 PRINT "Name of last file is: ",File_name$
275 INPUT "File to be used? Don't type suffix B,C,or Z.",File_name$
276 Xfile$=File_name$&"B"
277 Yfile$=File_name$&"C"
278 Zfile$=File_name$&"Z"
279 Qfile$=File_name$&"Q"
280 ASSIGN @Path1 TO Xfile$
281 ASSIGN @Path2 TO Yfile$
282 ASSIGN @Path3 TO Zfile$
283 ASSIGN @Path4 TO Qfile$
284 ON END @Path4 GOTO Main_menu
285 OFF ERROR
286 ON ERROR GOTO 288
287 OUTPUT @Path1;Strain(*)
288 OFF ERROR
289 ON ERROR GOTO 291
290 OUTPUT @Path2;Stress(*)
291 OFF ERROR
292 ON ERROR GOTO 296
293 E_c=Ex_convert
294 E_i=Ex_inter
295 OUTPUT @Path3;Sample_nr$,X_axis$,Y_axis$,Dia,Wide,Thick,Gauqe,T_start,T_end,Load_min,Load_max,Fs_load_cell,Te_co,Str_rate,Extensometer$,E_c,E_i,Test_temp
296 OFF ERROR
297 ON ERROR GOTO 300
298 OUTPUT @Path4;Extens(*)
299 OFF ERROR
300 ASSIGN @Path4 TO *
301 ASSIGN @Path1 TO *
302 ASSIGN @Path2 TO *
303 ASSIGN @Path3 TO *
304 MASS STORAGE IS ":CS80,700,1"
305 GOTO Main_menu
306 Store_err: !
307 PRINTER IS 1
308 IF ERRN=56 THEN
309 OFF ERROR
310 PRINT "File not found. Below is a list of current files."
311 CAT
312 FOR Q=1 TO 5
313 PRINT
314 NEXT Q
315 PRINT "Would you like to create a new file? <Y> if this is new data"
316 GOSUB Yes_no
317 IF Answer$="Y" THEN

```

```

318     PRINT "Insert data disk"
319     BEEP
320 New_file:      !
321     ON ERROR GOTO Disk_full
322     PRINT "Creating new files....."
323     CREATE BOAT File_name$&"B",8,N_points
324     CREATE BOAT File_name$&"C",8,N_points
325     CREATE BOAT File_name$&"Z",1,100!ITS STILL LESS THAN 1000
326     CREATE BOAT File_name$&"Q",1,N_points
327     OFF ERROR IN_points is the # of data points acquired
328     ELSE
329         GOTO Store_data
330     END IF
331     ELSE
332         PRINT ERRMS$
333         OFF ERROR
334         PRINT "Do you want to try again?"
335         GOSUB Yes_no
336         IF Answer$="Y" THEN Store_data
337         GOTO Main_menu
338     END IF
339     PRINT USING "@,%"
340     BEEP
341     GOTO Store_data
342 Disk_full:      !
343     OFF ERROR
344     PRINT "This disk is full. Do you want to replace it with a new disk?"
345     GOSUB Yes_no
346     IF Answer$="N" THEN Store_data
347     GOTO New_file
348 Print_data:      !
349     PRINTER IS 701
350     GOSUB Show_set_up_2
351     PRINTER IS 1
352     GOTO Main_menu
353 Plot_data:      !
354     GOSUB Plot_set_up
355     L_type=0
356 Next_curve:      !
357     L_type=L_type+1
358     LINE TYPE L_type
359     OFF KEY
360     ON KEY 1 LABEL "ContinuePlot" GOTO Plot_data_2
361     ON KEY 2 LABEL "CHANGE MAINAXES" GOTO Plot_axes
362     ON KEY 3 LABEL " " GOTO Plot_data_idle
363     ON KEY 4 LABEL "NEW PLOT" GOTO Main_menu
364     ON KEY 5 LABEL "Main Menu" GOTO Main_menu
365     ON KEY 6 LABEL "Print Data" GOTO Print_data
366     IF Extensometer$="ON" THEN
367         ON KEY 7 LABEL "LOAD- STRAIN" GOTO Plot_data_3
368     ELSE

```

```

369     ON KEY 7 LABEL " " GOTO Plot_data_idle
370 END IF
371 ON KEY 8 LABEL "LOAD- TIME" GOTO Plot_data_2
372 KEY LABELS ON
373 Plot_data_idle:GOTO Plot_data_idle
374 Plot_axes: !
375 GOSUB Axes_u
376 GOSUB Start_t
377 GOSUB Plot_set_up
378 GOTO Plot_data_2
379 Sub_axes: !
380 GOSUB Ex_plt_cnv
381 GOSUB Plot_set_up
382 GOTO Plot_data_2
383 Plot_data_3: !
384 GOSUB Pen_select
385 KEY LABELS OFF
386 IF Answer$="Y" THEN GOSUB Pen_select
387 FOR I=1 TO 5000
388     Exploit=Extens(I)*Exp_cont+Exp_int
389     IF I=1 OR Exploit=T_start THEN MOVE Exploit,Stress(I)
390     IF Exploit<T_start OR Exploit>T_end THEN End_plot_3
391     PLOT Exploit,Stress(I)
392 End_plot_3: !
393 NEXT I
394 IF Answer$="Y" THEN PEN 0
395 GOTO Next_curve
396 Re_data_1: !
397 GOSUB Re_data
398 Plot_data_2: !
399 IF Which_pltr$="Plotter" THEN GOSUB Pen_select
400 KEY LABELS OFF
401 FOR I=1 TO 5000
402     IF I=N_points THEN GOTO Next_curve
403     IF I=1 OR Strain(I)=T_start THEN MOVE Strain(I),Stress(I)
404     IF Strain(I)<T_start THEN End_curve
405     IF Te_co=1 AND Stress(I)>Load_max OR Stress(I)<Load_min THEN GOTO End_
curve
406     IF Te_co=3 AND (Stress(I)<Load_max OR Stress(I)>Load_min) THEN GOTO End_
curve
407     IF Strain(I)>T_end THEN
408         I=5000
409         GOTO End_curve
410     END IF
411     IF I>N_points AND Strain(I)=0 THEN
412         GOTO Next_curve
413     END IF
414     PLOT Strain(I),Stress(I)
415 End_curve: !
416 NEXT I
417 IF Answer$="Y" THEN PEN 0
418 GOTO Next_curve
419 Show_set_up_1: !

```



```

421 GOSUB Show_set_up
422 GOTO Main_menu_idle
423 Stopped: !
424 PRINTER IS 1
425 KEY LABELS OFF
426 PRINT "Do you want to reduce data or use another program?"
427 GOSUB Yes_no
428 IF Answer$="Y" THEN LOAD "MSLABS"
429 STOP
430 Load_cell: !
431 KEY LABELS OFF
432 INPUT "What is the full-scale load value in kN?",Fs_load_cell
433 GOTO Main_menu
434 S_area: !
435 OFF KEY
436 FOR Q=1 TO 4
437     ON KEY Q LABEL "round sample" GOTO Round
438     ON KEY Q+4 LABEL "rect. sample" GOTO Rect
439 NEXT Q
440 KEY LABELS ON
441 S_area_idle:GOTO S_area_idle
442 Round:!
443 KEY LABELS OFF
444 INPUT "Sample diameter, mm?",Dia
445 Sample_area=(PI/4)*(Dia^2)
446 GOTO G_length
447 Rect: !
448 KEY LABELS OFF
449 INPUT "Sample width, mm?",Wide
450 INPUT "Sample thickness, mm?",Thick
451 Sample_area=Wide*Thick
452 G_length: !
453 PRINT "Default gauge length is ",Gauge;" mm. Hit <RETURN> to accept"
454 INPUT "Gauge length, mm?",Gauge
455 RETURN
456 Show_set_up:!
457 PRINTER IS 1
458 Show_set_up_2: !
459 PRINT USING "@,@"
460 PRINT "Current set up is as follows:"
461 PRINT " Sample Parameters:"
462 IF Sample_nr$="" THEN
463     PRINT " Sample unnamed"
464 ELSE
465     PRINT " Sample: ";Sample_nr$
466 END IF
467 IF Gauge<>0 THEN
468     PRINT " Gauge length is ";Gauge;" mm"
469 ELSE
470     PRINT " No gauge length specified"
471 END IF
472 IF Dia<>0 THEN Sample_area=(PI/4)*(Dia^2)

```

```

473 IF Thick<>0 AND Wide<>0 THEN Sample_area=Wide*Thick
474 IF Sample_area<>0 THEN
475     IF Dia<>0 THEN
476         PRINT "      Using round samole with a diameter of ";Dia;" mm"
477     ELSE
478         PRINT "      Using flat sample ";Wide;" mm wide X ";Thick;"mm thick"
479     END IF
480     PRINT "      Sample area is ";Sample_area;" mm^2"
481 ELSE
482     PRINT "      Sample dimensions are incomplete"
483 END IF
484 PRINT
485 PRINT "      Testing Parameters:"
486 PRINT "      Crosshead speed";Str_rate;" mm/min"
487 PRINT "      Full-scale range of load cell is set for ";Fs_load_cell;"kN"
488 PRINT "      Hold time at finish ";Hold_time;" min"
489 IF Te_co=1 THEN PRINT "      Tension only test"
490 IF Te_co=2 THEN PRINT "      Tension/compression test"
491 IF Te_co=3 THEN PRINT "      Compression only test"
492 PRINT "      Extensometer/Strain Gage is ";Extensometer$
493 IF Extensometer$="On" THEN
494     PRINT "      Extensometer/Strain gage conversion factor is ";Ex_convert
495     PRINT "      Extensometer/Strain gage intercept is ";Ex_inter
496     PRINT "      Strain shown will be from ";Explot0;" to ";Explotmax
497 END IF
498 PRINT "      Test temperature is ";Test_temp;" deg C or ";Test_temp+273.15;
" K"
499 PRINT
500 PRINT "      Plotting Parameters:"
501 IF X_axis$="Time, minutes" THEN PRINT "      Start time ";T_start;" min   F
inish time ";T_end;" min"
502 IF X_axis$="Time, seconds" THEN PRINT "      Start time ";T_start;" sec   F
inish time ";T_end;" sec"
503 IF X_axis$="Elongation, mm" THEN PRINT "      Starting Elongation ",T_start
;" mm   Finish Elongation ";T_end;" mm"
504 IF X_axis$="Elongation, Percent" THEN PRINT "      Starting Elongation ",T_
start;" %   Finish Elongation ";T_end;" %"
505 IF X_axis$="Strain" THEN PRINT "      Starting strain ",T_star   Finish st
rain ";T_end
506 IF Y_axis$="Volts DC" THEN PRINT "      Y-axis minimum is ";L   :_mini" volt
s and Y-axis maximum is ";Load_max;" volts"
507 IF Y_axis$="Millivolts DC" THEN PRINT "      Y-axis minimum is ";Load_min;"
millivolts and Y-axis maximum is ";Load_max;" millivolts"
508 IF Y_axis$="Load, kN" THEN PRINT "      Load ranges from ",Load_min;" kN to
";Load_max;" kN (neg value means compression)"
509 IF Y_axis$="Stress, MPa" THEN
510     PRINT "      Stress ranges from ",Load_min;" MPa to ";Load_max;" MPa"
511     PRINT "      (neg value means compression)"
512 END IF
513 RETURN
514 Set_up_menu: !

```

```

515 BEEP 2000,.2
516 BEEP 2100,.2
517 OFF KEY
518 GOSUB Show_set_up
519 ON KEY 1 LABEL "Sample Params" GOTO Sample_id_s
520 ON KEY 2 LABEL "Sample Params" GOTO Sample_id_s
521 ON KEY 3 LABEL "Test Params" GOTO Test_params
522 ON KEY 4 LABEL "Test Params" GOTO Test_params
523 ON KEY 5 LABEL "PlottingParams" GOTO Axes_units
524 ON KEY 6 LABEL "PlottingParams" GOTO Axes_units
525 ON KEY 7 LABEL "" GOTO Set_up_idle
526 ON KEY 8 LABEL "SETUP OK" GOTO Main_menu
527 IF Sample_nr$="" THEN ON KEY 8 LABEL "IDENTIFYSAMPLE" GOTO Sample_id_s
528 IF (Y_axis$="Load, kN" OR Y_axis$="Stress, MPa") AND Fs_load_cell=0 THEN
529   ON KEY 8 LABEL "NEED LOADCELL" GOTO Load_cell
530   BEEP 2000,.1
531 END IF
532 IF (Y_axis$="Stress, MPa" AND Sample_area=0) OR (X_axis$="Elongation, %" OR
R X_axis$="Strain" AND Gauge=0) THEN
533   ON KEY 8 LABEL "SAMPLE OIMEN." GOTO S_area_2
534 END IF
535 IF (X_axis$="Elongation, mm" OR X_axis$="Elongation, %" OR X_axis$="Strain
") AND Str_rate=0 THEN
536   ON KEY 7 LABEL "X-head Speed" GOTO Rates
537   ON KEY 8 LABEL "" GOTO Rates
538 END IF
539 KEY LABELS ON
540 Set_up_idle:GOTO Set_up_idle
541 Test_params: !
542 ON KEY 1 LABEL "Change X-head V" GOTO Rates
543 ON KEY 2 LABEL "Change Load Cell" GOTO Load_cell
544 ON KEY 3 LABEL "Tension/Compression" GOTO Ten_com
545 ON KEY 4 LABEL "Hold Time" GOTO Holds
546 ON KEY 5 LABEL "Extens. Toggle" GOTO Extoggle_1
547 FOR Q=6 TO 8
548   ON KEY Q LABEL "" GOTO Test_par_spin
549 NEXT Q
550 Test_par_spin:GOTO Test_par_spin
551 Extoggle_1: !
552 GOSUB Ex_toggle
553 GOSUB Ex_cnv
554 GOSUB Ex_plt_cnv
555 GOTO Set_up_menu
556 G_1_set_up: !
557 Var=Gauge
558 PRINT "Changing gauge length"
559 GOSUB Var_change
560 Gauge=Var
561 GOTO Set_up_menu
562 Start_t: !
563 Var=T_start

```

```

564 PRINT "Changing minimum x-axis value:"
565 GOSUB Var_change
566 T_start=Var
567 Var=T_end
568 PRINT "Changing maximum x-axis value:"
569 GOSUB Var_change
570 T_end=Var
571 T_ran=T_end-T_start
572 Load_vals: I
573 Var=Load_min
574 PRINT "Changing minimum y-axis value:"
575 GOSUB Var_change
576 Load_min=Var
577 Var=Load_max
578 PRINT "Changing maximum y-axis value:"
579 GOSUB Var_change
580 Load_max=Var
581 Load_ran=Load_max-Load_min
582 RETURN
583 Axes_units: I
584 GOSUB Axes_u
585 GOSUB Start_t
586 GOTO Set_up_menu
587 Axes_u: I
588 KEY LABELS OFF
589 OFF KEY
590 PRINT "Select label for X-axis. Default is time in minutes"
591 ON KEY 1 LABEL "Time Minutes" GOTO Time_min
592 ON KEY 2 LABEL "Time Seconds" GOTO Time_sec
593 ON KEY 3 LABEL "Elong. mm" GOTO Elong_mm
594 ON KEY 4 LABEL "Elong. %" GOTO Elong_pct
595 ON KEY 5 LABEL "Strain" GOTO Strain_axis
596 FOR Q=6 TO 8
597 ON KEY Q LABEL "" GOTO Axes_idle
598 NEXT Q
599 KEY LABELS ON
600 Axes_idle:GOTO Axes_idle
601 Time_min:I
602 X_axis$="Time, minutes"
603 GOTO Set_up_y_axis
604 Time_sec:I
605 X_axis$="Time, seconds"
606 GOTO Set_up_y_axis
607 Elong_mm:I
608 X_axis$="Elongation, mm"
609 GOTO Set_up_y_axis
610 Elong_pct:I
611 X_axis$="Elongation, Percent"
612 GOTO Set_up_y_axis
613 Strain_axis:I
614 X_axis$="Strain"

```

```

615 Set_up_y_axis: I
616   OFF KEY
617   PRINT "Select label for Y-axis. Default is load"
618   ON KEY 3 LABEL "Volts DC" GOTO Volts_y
619   ON KEY 4 LABEL "mV DC" GOTO Mv_y
620   ON KEY 1 LABEL "Load, kN" GOTO Load_y
621   ON KEY 2 LABEL "Stress, MPa" GOTO Stress_y
622   FOR Q=5 TO 8
623     ON KEY Q LABEL "" GOTO Y_ax_idle
624   NEXT Q
625   KEY LABELS ON
626 Y_ax_idle: GOTO Y_ax_idle
627 Volts_y: I
628   Y_axis$="Volts DC"
629   RETURN
630 Mv_y: I
631   Y_axis$="Millivolts DC"
632   RETURN
633 Load_y: I
634   Y_axis$="Load, kN"
635   RETURN
636 Stress_y: I
637   Y_axis$="Stress, MPa"
638   RETURN
639 Rates: I
640   Var=Str_rate
641   PRINT "Editing crosshead speed: give value in mm/min"
642   GOSUB Var_change
643   Str_rate=Var
644   GOTO Set_up_menu
645 Holds: I
646   GOSUB Holds1
647   GOTO Set_up_menu
648 Holds1: I
649   PRINT "Change hold time?"
650   GOSUB Yes_no
651   IF Answer$="Y" THEN
652     Var=Hold_time
653     GOSUB Var_change
654     Hold_time=Var
655   END IF
656   RETURN
657 Ex_toggle: I
658   PRINT "Toggle extensometer?"
659   GOSUB Yes_no
660   IF Answer$="N" THEN 658
661   IF Extensometer$="Off" THEN
662     Extensometer$="On"
663   ELSE
664     Extensometer$="Off"
665   END IF

```



```

666 RETURN
667 Ex_cnv: !
668 IF Extensometer$="On" THEN
669 PRINT "Change conversion factor?"
670 GOSUB Yes_no
671 IF Answer$="Y" THEN
672 Var=Ex_convert
673 GOSUB Var_change
674 Ex_convert=Var
675 END IF
676 PRINT "Change intercept?"
677 GOSUB Yes_no
678 IF Answer$="Y" THEN
679 Var=Ex_inter
680 GOSUB Var_change
681 Ex_inter=Var
682 END IF
683 END IF
684 RETURN
685 Ex_plt_cnv: !
686 IF Extensometer$="On" THEN
687 PRINT "Change minimum strain plotted?"
688 GOSUB Yes_no
689 IF Answer$="Y" THEN
690 Var=Explot0
691 GOSUB Var_change
692 Explot0=Var
693 END IF
694 PRINT "Change maximum strain plotted?"
695 GOSUB Yes_no
696 IF Answer$="Y" THEN
697 Var=Explotmax
698 GOSUB Var_change
699 Explotmax=Var
700 END IF
701 Exo_con=(T_start-T_end)/(Explot0-Explotmax)
702 Exo_int=T_start-Explot0*Exo_con
703 END IF
704 RETURN
705 Ten_com: !
706 KEY LABELS OFF
707 PRINT "TENSION, TENSION/COMPRESSION OR COMPRESSION TEST?"
708 BEEP 2000,.1
709 OFF KEY
710 ON KEY 1 LABEL "TENSION" GOTO Ten_only
711 ON KEY 2 LABEL "TENSION" GOTO Ten_only
712 ON KEY 3 LABEL "" GOTO Ten_idle
713 ON KEY 4 LABEL "TENSION/COMPRESS" GOTO Ten_and_com
714 ON KEY 5 LABEL "TENSION/COMPRESS" GOTO Ten_and_com
715 ON KEY 6 LABEL "" GOTO Ten_idle
716 ON KEY 7 LABEL "COMPRESS" GOTO Com_only

```

```

717 ON KEY 8 LABEL "COMPRESS" GOTO Com_only
718 KEY LABELS ON
719 Ten_idle:GOTO Ten_idle
720 Ten_only:Te_co=1
721 GOTO Set_up_menu
722 Ten_and_com:Te_co=2
723 GOTO Set_up_menu
724 Com_only:Te_co=3
725 GOTO Set_up_menu
726 Var_change:!
727 INPUT "Type in desired value",Var
728 PRINTER IS 1
729 PRINT Var;"Is this OK?"
730 GOSUB Yes_no
731 IF Answer$="N" THEN Var_change
732 RETURN
763 Set_up_ok:!
764 Init_daq:!
765 KEY LABELS OFF
766 GOSUB Plot_set_up
767 OUTPUT 709;"CLR"
768 OUTPUT 709;"USE 000"
769 PRINTER IS 1
770 Re_test: !
771 Acq_data:!
772 IF Which_pltr$="CRT" THEN
773   Penn$="Data"
774   GOSUB Pen_select
775 END IF
776 FOR Q=1 TO 4
777   ON KEY Q LABEL "TEST   COMPLETE" GOTO Test_done
778   ON KEY Q+4 LABEL "RE-STARTTEST" GOTO Re_test
779 NEXT Q
780 KEY LABELS ON
781 T_total=T_end-T_start
782 T_convert=1 !assumes x-axis is in seconds
783 IF X_axis$="Time, minutes" THEN T_convert=1/60
784 IF X_axis$="Elongation, mm" THEN T_convert=Str_rate/60
785 IF X_axis$="Elongation, %" THEN T_convert=(Str_rate/Gauge)*(100/60)
786 IF X_axis$="Strain" THEN T_convert=(Str_rate/60)/Gauge
787 L_convert=1 !assumes DCV is output
788 IF Y_axis$="Millivolts DC" THEN L_convert=1000
789 IF Y_axis$="Load, kN" THEN L_convert=Fs_load_cell/10
790 IF Y_axis$="Stress, MPa" THEN L_convert=(Fs_load_cell*100)/Sample_area
791 KEY LABELS OFF
792 INPUT "Hit <RETURN> when ready to proceed.",Which$
793 KEY LABELS ON
794 T_0=TIMEDATE !Time is measured in seconds then converted to desired unit
795 LONG S

```

```

796   FOR I=0 TO 5000
797     REPEAT
798       T_1=(TIME0ATE-T_0)*T_convert
799       UNTIL T_1)=(T_total/5000)*(I)
800       Strain(I)=T_1
801       OUTPUT 709;"CONFMEAS DCV,214"
802       ENTER 709;Stress(I)
803       Stress(I)=Stress(I)*L_convert
804       PLOT Strain(I),Stress(I)
805       IF Extensometer$="On" THEN
806         OUTPUT 709;"CONFMEAS DCV,215"
807         ENTER 709;Extens(I)
808         Extens(I)=Extens(I)*Ex_convert+Ex_inter!CONVERTS TO STRAIN VALUES
809         ExpIot=Extens(I)*Exp_con+Exp_int!CONVERTS STRAIN TO PLOTABLE VALUES
810         MOVE ExpIot      15(I)
811         LABEL USING      15"
812       ENO IF
813     NEXT I
814   Test_done: !
815   N_points=I!THIS IS THE LAST DATA POINT ACQUIRED
816   OFF KEY !      AND THE PLOTTER DOESN'T GO NUTS
817   FOR Q=1 TO 4
818     ON KEY Q LABEL "      " GOTO Oumper!OUMP PLOT???
819     ON KEY Q+4 LABEL "Main Menu" GOTO Main_menu
820   NEXT Q
821   T_d_idle:GOTO T_d_idle
822   Pen_select: !
823   ON KEY 1 LABEL "Pen 1" GOTO P1
824   ON KEY 2 LABEL "Pen 2" GOTO P2
825   ON KEY 3 LABEL "Pen 3" GOTO P3
826   ON KEY 4 LABEL "Pen 4" GOTO P4
827   ON KEY 5 LABEL "Pen 5" GOTO P5
828   ON KEY 6 LABEL "Pen 6" GOTO P6
829   ON KEY 7 LABEL "Drawing "&Penn$ GOTO Pen_select_idle
830   ON KEY 8 LABEL "Drawing "&Penn$ GOTO Pen_select_idle
831   KEY LABELS ON
832   BEEP 2000,.1
833   Pen_select_idle:GOTO Pen_select_idle
834   P1:PEN 1
835   GOTO Pen_return
836   P2:PEN 2
837   GOTO Pen_return
838   P3:PEN 3
839   GOTO Pen_return
840   P4:PEN 4
841   GOTO Pen_return
842   P5:PEN 5
843   GOTO Pen_return
844   P6:PEN 6
845   Pen_return: !
846   KEY LABELS OFF

```

```

847 RETURN
848 Dumper: 1
849 KEY LABELS OFF
850 DUMP DEVICE IS 701
851 OUTPUT K80;"N";
852 GOTO Main_menu
853 File_err: !
854 PRINTER IS 1
855 PRINT USING "@,@"
856 BEEP 2000,.3
857 IF ERRN=78 OR ERRN=85 THEN
858     PRINT "WARNING you are initializing this disc. All data will be erased."
859     INPUT "Hit <RETURN> to continue",Which$
860     INITIALIZE ":CS80,700,1"
861 END IF
862 PRINT "Error in file name selection",ERRN,ERRM$
863 GOTO Data_save
864 Plot_set_up: !
865 PRINTER IS 1
866 OFF KEY
867 PRINT "Do you want to use the Plotter?"
868 GOSUB Yes_no
869 OUTPUT K80;"K";
870 IF Answer$="Y" THEN INPUT "Put paper in the plotter then hit <RETURN>",Which$
871 GINIT
872 GRAPHICS ON
873 IF Answer$="Y" THEN
874     PLOTTER IS 705,"HPGL"
875     VIEWPORT 0,125,0,100
876     Which_pltr$="Plotter"
877     Penn$="Axes"
878     GOSUB Pen_select
879 ELSE
880     PLOTTER IS CRT,"INTERNAL"
881     Which_pltr$="CRT"
882     VIEWPORT 0,120,26,100
883 ENO IF
884 Load_ran=Load_max-Load_min
885 T_ran=T_end-T_start
886 WINDOW T_start-.1*(T_ran),T_end,Load_min-.1*Load_ran,Load_max+.13*Load_ran
887 CLIP T_start,T_end,Load_min,Load_max
888 GRID T_ran/10,Load_ran/10,T_start,Load_min,1,1
889 CLIP OFF
890 CSIZE 3
891 LORG 4
892 MOVE (T_start+T_end)/2,Load_max+.08*Load_ran
893 LABEL USING "K";Sample_nr$& " "&VAL$(Test_temp)&" C"
894 LORG 6
895 FOR I=T_start TO T_end STEP (T_start-T_end)/(-5)

```

```

896     MOVE I,Load_min-.025*Load_ran
897     LABEL USING "K";I
898     NEXT I
899     MOVE .5*(T_start+T_end),Load_min-.07*Load_ran
900     LABEL USING "K";X_axis$
901     LORG 8
902     FOR I=Load_min TO Load_max STEP Load_ran/10
903         MOVE T_start-(.01*(T_end-T_start)),I
904         LABEL USING "K";I
905     NEXT I
906     LORG 4
907     MOVE T_start-(.07*(T_end-T_start)),Load_ran/2+Load_min
908     DEG
909     LDIR 90
910     LABEL USING "K";Y_axis$
911     LDIR 0
912     LORG 4
913     IF Extensometer$="On" THEN
914         Exp_ran=Explo_tmax-Explo_t0
915         CLIP T_start+.1*T_ran,T_end,Load_max,Load_max+.1*Load_ran
916         AXES T_ran/10,Load_ran/20,T_start,Load_max
917         CLIP OFF
918         FOR I=T_start TO T_end STEP T_ran/10
919             MOVE I,Load_max+Load_ran*.03
920             LABEL USING "K";(I-Exp_int)/Exp_con
921         NEXT I
922     END IF
923     RETURN
924 Which_msu: !
925     MASS STORAGE IS ":CS80,700,1"
926     PRINT "Do you want to store/recall data to/from the 3-1/2 floppy?"
927     GOSUB Yes_no
928     IF Answer$="Y" THEN MASS STORAGE IS ":CS80,700"
929     KEY LABELS OFF
930     RETURN
931 Yes_no: !
932     OFF KEY
933     KEY LABELS OFF
934     FOR Q=1 TO 4
935         ON KEY Q LABEL "YES" GOTO Yess
936         ON KEY Q+4 LABEL "NO" GOTO Noo
937     NEXT Q
938     KEY LABELS ON
939     Yes_no_idle:GOTO Yes_no_idle
940     Yess:Answer$="Y"
941     RETURN
942     Noo:Answer$="N"
943     RETURN
944 Analyze_data: !
945     PRINTER IS 1
946     PRINT "Data analysis section not written yet"

```



```
947 BEEP
948 GOTO Main_menu
949 END
950 SUB Changer(Ara(*),F)
951   FOR I=1 TO 5000
952     Ara(I)=Ara(I)*F
953   NEXT I
954 SUBEND
```

B. DATA REDUCTION PROGRAM

REDUCE is similar in structure to ACQR. The load/time data stored by ACQR is accessed and converted to stress/strain data.

1. Users Guide

The program is used similarly to ACQR. The user recalls the data of interest and plots it on the video screen and then selects 'REDUCE DATA' from the menu. The elastic range of the plot needs to be linearized. This is done through 'INPUT TYPE' by 1) a numerical X-Y input via the keyboard, 2) using the cursor arrows, or 3) by using the mouse. The end points of the line is selected and the last good data point is chosen. The line is then drawn over the plot. If the slope of the plastic zone is not correct, it can be done over or accepted using 'SLOPE OKAY'. The program will remove the grip slippage and re-zero the plot and display the true stress vs. true strain plot that has been "reduced" from the rough load vs. time plot by using 'PLOT TRUE'. Do not select the plotter until you have changed the axes to the appropriate units. The program prints the maximum true stress and true strain of the data at the top of the graph. Round up to convenient, easily divisible numbers for the axes. Also choose 'TRUE STRESS' and 'TRUE STRAIN' for the axes labels. You may then make a hard copy plot.

2. Source Listing

```
10      I Program to convert load/time to stress/strain from the Instron 6027
21      I Revised 07DEC90 Paul Macri
25      I REDUCE (Stored as S24JUL)
30      DIM Strain(5000),Stress(5000),Sample_nr$(50),Area_i(5000),Extens(5000)
35      I note: Extens is used for inputting strain gage data
37      DIM Stress_engr(5000),Strain_engr(5000),Stress_true(5000)
38      DIM Strain_true(5000)
40      DIM X_axis$(25)
41      CLEAR SCREEN
45 Init_sec: I
50      Str_rate=1.07 !mm/min
55      Gauge=12.7 !gauge length in mm
60      T_start=0
65      T_end=1000
70      T_total=1000
75      Load_min=0
80      Load_max=2
85      Fs_load_cell=20
90      Test_temp=300
95      X_axis$="Time, minutes"
100     Y_axis$="Load, kN"
```

```

105 Te_co=1 ITENSION ONLY TEST
110 Extensometer$="Off"
115 Ex_convert=1
120 Ex_inter=0
125 Exp_con=1
130 Exp_int=0
135 Explo0=0
140 Lxplotmax=20
145 Wide=0
150 Thick=0
151 Zzz=0! TELLS WHAT THE MAX STRESS/STRAIN IS FOR AXES
153 Xx=0! THIS IS FOR THE X,Y AXIS LABELS FOR TRUE/ENGR
154 Old_axes=2! 2 MEANS CREATE AXES FOR A NEW PLOT
155 ! 3 MEANS YOU WANT TO SUPERIMPOSE SEVERAL PLOTS
156 GOSUB Show_set_up
157 !***** MAIN MENU *****
160 Main_menu: !
165 BEEP 2000,.1
170 OFF KEY
175 ON KEY 1 LABEL "Change Set-up" GOTO Set_up_menu! LINE 3050
180 ON KEY 2 LABEL "Show Set-up" GOTO Show_set_up_q! LINE ?
185 ON KEY 3 LABEL "Change Data" GOTO Change_data! LINE 315
190 ON KEY 4 LABEL "QUIT" GOTO Stopper! LINE 2595
195 ON KEY 5 LABEL "Store Data" GOTO Store_data! LINE 1870
200 ON KEY 6 LABEL "Plot Oata" GOTO Plot_data! LINE 2380
205 ON KEY 7 LABEL "Recall Old Data" GOTO Recall_data! LINE 1620
210 ON KEY 8 LABEL "RUN/ REDUCE" GOTO Set_up_ok!
218 IF (Y_axis$="Load, kN" OR Y_axis$="Stress, MPa") AND Fs_load_cell=0 THEN
220 ON KEY 7 LABEL "NEED LOADCELL" GOTO Load_cell
225 ON KEY 8 LABEL "DATA NEEEO" GOTO Main_menu
230 BEEP 2000,.1
235 BEEP 2500,.1
240 END IF
245 IF (Sample_area=0 OR Gauge=0) THEN
250 ON KEY 3 LABEL "NEED SA.OIMEN." GOTO S_area_1
255 ON KEY 8 LABEL "OATA NEEEO" GOTO Main_menu
260 BEEP 2000,.1
265 BEEP 2500,.1
270 END IF
275 IF Sample_nr$="" THEN
280 ON KEY 4 LABEL "IOENTIFYSAMPLE" GOTO Sample_id_m
285 ON KEY 8 LABEL "OATA NEEEO" GOTO Main_menu
290 BEEP 2000,.1
295 BEEP 2500,.1
300 ENO IF
301 KEY LABELS ON
310 Main_menu_idle:GOTO Main_menu_idle
312 Change_data: !***** CHANGE DATA *****
320 OFF KEY
325 ON KEY 1 LABEL "ADD 10%" GOTO C_d_add101 $$$$$$ CHANGE LATER
330 ON KEY 2 LABEL "ADD 50%" GOTO C_d_add50

```

```

335 ON KEY 3 LABEL "SUB. 10%" GOTO C_d_sub10
340 ON KEY 4 LABEL "SUB. 50%" GOTO C_d_sub50
345 ON KEY 5 LABEL "MULTIPLYBY 0.1 " GOTO C_d_mulp1
350 ON KEY 6 LABEL "MULTIPLYBY 2 " GOTO C_d_mul2
355 ON KEY 7 LABEL "MULTIPLYBY 10" GOTO C_d_mul10
360 ON KEY 8 LABEL "Convert Units" GOTO Conv_units
365 KEY LABELS ON
370 C_d_spin:GOTO C_d_spin
375 C_d_add10:C_d_mult=1.1
380 GOTO C_d
385 C_d_add50:C_d_mult=1.5
390 GOTO C_d
395 C_d_sub10:C_d_mult=.9
400 GOTO C_d
405 C_d_sub50:C_d_mult=.5
410 GOTO C_d
415 C_d_mulp1:C_d_mult=.1
420 GOTO C_d
425 C_d_mul2:C_d_mult=2
430 GOTO C_d
435 C_d_mul5:C_d_mult=5
440 GOTO C_d
445 C_d_mul10:C_d_mult=10
450 C_d:***** C_D *****
455 OFF KEY
460 FOR Q=1 TO 2
465 ON KEY Q LABEL "CHANGE X-VALUES" GOTO C_d_chq_x! LINE 495
470 ON KEY Q+2 LABEL "CHANGE Y-VALUES" GOTO C_d_chq_y! LINE 505
475 ON KEY Q+4 LABEL "CHANGE AREAS" GOTO C_d_chq_z! LINE 515
480 NEXT Q
485 KEY LABELS ON
490 C_d_idle:GOTO C_d_idle
495 C_d_chq_x:CALL Changer(Strain(*),C_d_mult)
500 GOTO Main_menu
505 C_d_chq_y:CALL Changer(Stress(*),C_d_mult)
510 GOTO Main_menu
515 C_d_chq_z:CALL Changer(Area_i(*),C_d_mult)
520 GOTO Main_menu!***** CONV_UNI *****
525 Conv_units: ! Converts x-axis units from current units to in, load, etc
530 INPUT "Specify code to use conversion section",Which$
535 IF Which$<>"CODE" AND Which$<>"Code" AND Which$<>"code" Main_menu
540 ON KEY 1 LABEL "Conv. toLoad-t" GOTO Load_time
545 ON KEY 2 LABEL "Conv. toLoad-ext" GOTO Load_ext
550 ON KEY 3 LABEL "Conv. toLoad-%" GOTO Load_pct
555 ON KEY 4 LABEL "Conv. toLoad-strn" GOTO Load_strain
560 ON KEY 5 LABEL "Conv. toStrs-X" GOTO Stress_pct
565 ON KEY 6 LABEL "Conv. toStrs-ext" GOTO Stress_ext
570 ON KEY 7 LABEL "Conv. toStrs-strn" GOTO Stress_strain
575 ON KEY 8 LABEL "Conv. toTrue S-s" GOTO True_true
580 KEY LABELS ON
585 Conv_units_idle:GOTO Conv_units_idle

```

```

590 Load_time!
595 GOSUB Conv_time_1
600 GOSUB Conv_load_1
605 GOTO Main_menu
610 Load_ext: !
615 GOSUB Conv_load_1
620 GOSUB Conv_ext_1
625 GOTO Main_menu
630 Load_pct!
635 GOSUB Conv_load_1
640 GOSUB Conv_pct_1
645 GOTO Main_menu
650 Load_strain:!
655 GOSUB Conv_load_1
660 GOSUB Conv_strain_1
665 GOTO Main_menu
670 Stress_pct:!
675 GOSUB Conv_stress_1
680 GOSUB Conv_pct_1
685 GOTO Main_menu
690 Stress_ext:!
695 GOSUB Conv_stress_1
700 GOSUB Conv_ext_1
705 GOTO Main_menu
710 Stress_strain:!
715 GOSUB Conv_stress_1
720 GOSUB Conv_strain_1
725 GOTO Main_menu
730 True_true:!
735 PRINT "Not written yet"
740 BEEP 200,.5
745 WAIT 1
750 GOTO Main_menu
755 Conv_ext_1:! Converts x-data to extension in mm
760 KEY LABELS OFF
765 IF X_axis$="Elongation, mm" THEN GOTO Conv_ext_2
770 I_conv_x=1
775 IF X_axis$="Time, minutes" THEN
780 X_axis$="Elongation, mm"
785 I_conv_x=Str_rate
790 END IF
795 IF X_axis$="Time, seconds" THEN
800 X_axis$="Elongation, mm"
805 I_conv_x=Str_rate/60
810 END IF
815 IF X_axis$="Elongation, Percent" THEN
820 X_axis$="Elongation, mm"
825 I_conv_x=.01*Gauge
830 END IF
835 IF X_axis$="Strain" THEN
840 X_axis$="Elongation, mm"

```



```

845     I_conv_x=Gauge
850     END IF
855     IF I_conv_x=1 THEN GOSUB Con_err
860     GOSUB Conv_x
865     Conv_ext_2:RETURN
870     Conv_strain_1: Converts x-data to strain
875     GOSUB Conv_pct_1
880     I_conv_x=.01
885     X_axis$="Strain, mm/mm"
890     GOSUB Conv_x
895     RETURN
900     Conv_pct_1: Converts x-data to pct strain
905     KEY LABELS OFF
910     IF X_axis$="Elongation, Percent" THEN GOTO Conv_pct_2
915     I_conv_x=1
920     IF X_axis$="Time, minutes" THEN
925         X_axis$="Elongation, Percent"
930         I_conv_x=100*Str_rate/Gauge
935     END IF
940     IF X_axis$="Time, seconds" THEN
945         X_axis$="Elongation, Percent"
950         I_conv_x=100*(Str_rate/60)/Gauge
955     END IF
960     IF X_axis$="Elongation, mm" THEN
965         X_axis$="Elongation, Percent"
970         I_conv_x=100/Gauge
975     END IF
980     IF X_axis$="Strain" THEN
985         X_axis$="Elongation, Percent"
990         I_conv_x=100
995     END IF
1000    IF I_conv_x=1 THEN GOSUB Con_err
1005    GOSUB Conv_x
1010    Conv_pct_2:RETURN
1015    Conv_time_1: Converts x-data to time in minutes
1020    KEY LABELS OFF
1025    IF X_axis$="Time, minutes" THEN GOTO Conv_time_2
1030    I_conv_x=1
1035    IF X_axis$="Time, seconds" THEN
1040        X_axis$="Time, minutes"
1045        I_conv_x=1/60
1050    END IF
1055    IF X_axis$="Elongation, mm" THEN
1060        X_axis$="Time, minutes"
1065        I_conv_x=1/Str_rate
1070    END IF
1075    IF X_axis$="Elongation, Percent" THEN
1080        X_axis$="Time, minutes"
1085        I_conv_x=(1/Str_rate)*.01*Gauge
1090    END IF
1095    IF X_axis$="Strain" THEN

```

```

1100   X_axis$="Time, minutes"
1105   I_conv_x=(1/Str_rate)*Gauge
1110   END IF
1115   IF I_conv_x=1 THEN GOSUB Con_err
1120   GOSUB Conv_x
1125   Conv_time_2:RETURN
1130   Conv_stress_1:
1135   GOSUB Conv_load_1
1140   IF Sample_area=0 THEN GOSUB S_area
1145   I_conv_y=1000/Sample_area
1150   Y_axis$="Stress, MPa"
1155   GOSUB Conv_y
1160   RETURN
1165   Conv_load_1:
1170   IF Y_axis$="Load, kN" THEN Conv_load_2
1175   I_conv_y=1
1180   IF Y_axis$="Volts DC" THEN
1185     Y_axis$="Load, kN"
1190     IF Fs_load_cell=0 THEN INPUT "Full-scale value of load cell?, kN",Fs_load_cell
1195     I_conv_y=Fs_load_cell/10
1200   END IF
1205   IF Y_axis$="Millivolts DC" THEN
1210     Y_axis$="Load, kN"
1215     IF Fs_load_cell=0 THEN INPUT "Full-scale value of load cell?, kN",Fs_load_cell
1220     I_conv_y=Fs_load_cell/10000
1225   END IF
1230   IF Y_axis$="Stress, MPa" THEN
1235     Y_axis$="Load, kN"
1240     IF Sample_area=0 THEN GOSUB S_area
1245     I_conv_y=Sample_area
1250   END IF
1255   IF I_conv_y=1 THEN GOSUB Con_err
1260   GOSUB Conv_y
1265   Conv_load_2:RETURN
1270   Conv_x:
1275   FOR I=0 TO 5000
1280     Strain(I)=Strain(I)*I_conv_x
1285   NEXT I
1290   RETURN
1295   Conv_y:
1300   FOR I=0 TO 5000
1305     Stress(I)=Stress(I)*I_conv_y
1310   NEXT I
1315   RETURN
1320   Con_err:
1325   GOTO 200.5
1330   PRINTER IS 1
1335   PRINT "*****CAUTION*****No conversion"
1340   WAIT 3

```

```

1345 RETURN
1350 Load_time_2: I
1355 IF Y_axis$="Load, kN" THEN Load_time_3
1360 I_conv_y=1
1365 IF Y_axis$="Volts DC" THEN
1370   Y_axis$="Load, kN"
1375   IF Fs_load_cell=0 THEN INPUT "Full-scale value of load cell?, kN",Fs_load_cell
1380   I_conv_y=Fs_load_cell/10
1385 ENO IF
1390 IF Y_axis$="Millivolts DC" THEN
1395   Y_axis$="Load, kN"
1400   IF Fs_load_cell=0 THEN INPUT "Full-scale value of load cell?, kN",Fs_load_cell
1405   I_conv_y=Fs_load_cell/10000
1410 END IF
1415 IF Y_axis$="Stress, MPa" THEN
1420   Y_axis$="Load, kN"
1425   IF Sample_area=0 THEN GOSUB S_area
1430   I_conv_y=Sample_area
1435 ENO IF
1440 IF I_conv_y=1 THEN GOSUB Con_err
1445 GOSUB Conv_y
1450 Load_time_3:RETURN
1455 Sample_id_s: !***** SAMPLE_ID_S *****
1460 ON KEY 1 LABEL "IdentifySample" GOTO Sample_id_s_2
1465 ON KEY 2 LABEL "IdentifySample" GOTO Sample_id_s_2
1470 ON KEY 3 LABEL "Change Temp" GOTO Chq_test_temp
1475 ON KEY 4 LABEL "Change Temp" GOTO Chq_test_temp
1480 FOR Q=5 TO 8
1485   ON KEY Q LABEL "Change Dimen's" GOTO S_area_2
1490 NEXT Q
1495 Sample_id_spin:GOTO Sample_id_spin
1500 Chq_test_temp: I
1505 Var=Test_temp
1510 GOSUB Var_change
1515 Test_temp=Var
1520 GOTO Set_up_menu
1525 Sample_id_s_2: I
1530 GOSUB Sample_id
1535 GOTO Set_up_menu
1540 Sample_id_m: I
1545 GOSUB Sample_id
1550 GOTO Main_menu
1555 Sample_id: I
1560 KEY LABELS OFF
1565 INPUT "Identify sample 50 characters max",Sample_nr$
1570 RETURN
1575 S_area_1: I
1580 GOSUB S_area
1585 GOTO Main_menu

```

```

1590 S_area_2: 1
1595 GOSUB S_area
1600 GOTO Set_up_menu
1605 Show_set_up_q: 1
1610 GOSUB Show_set_up
1615 GOTO Main_menu
1620 Recall_data:1***** RECALL_DATA *****
1625 GOSUB Re_data
1626 GOSUB Show_set_up_n
1630 GOTO Plot_data
1635 Re_data:1***** RE DATA *****
1640 GOSUB Which_msu
1641 ON ERROR GOTO Input_err
1642 INPUT "File to be used? Don't type suffix X,Y,orZ.",File_names$
1643 Xfile$=File_names$&"B"
1644 Yfile$=File_names$&"C"
1645 Zfile$=File_names$&"Z"
1646 Qfile$=File_names$&"Q"
1647 ASSIGN @Path1 TO Xfile$
1648 ASSIGN @Path2 TO Yfile$
1649 ASSIGN @Path3 TO Zfile$
1650 ASSIGN @Path4 TO Qfile$
1651! ON ENO @Path3 GOTO Plot_data
1652 OFF ERROR
1653 ON ERROR GOTO 1655
1654 ENTER @Path1;Strain(*)
1655 OFF ERROR
1656 ON ERROR GOTO 1658
1657 ENTER @Path2;Stress(*)
1658 OFF ERROR
1659 ON ERROR GOTO 1663
1660 E_c=Ex_convert
1661 E_i=Ex_inter
1662 ENTER @Path3;Sample_nr$,X_axis$,Y_axis$,Dia,Wide,Thick,Gauge,T_start,T_end
,Load_min,Load_max,Fs_load_cell,Te_co,Str_rate,Extensometer$,E_c,E_i,Test_temp
1663 OFF ERROR
1664 ON ERROR GOTO 1667
1665 ENTER @Path4;Extens(*)
1666 OFF ERROR
1667 ASSIGN @Path4 TO *
1668 ASSIGN @Path1 TO *
1669 ASSIGN @Path2 TO *
1670 ASSIGN @Path3 TO *
1795 RETURN
1800 Input_err: 1*****INPUT_ERR *****
1805 PRINTER IS 1
1810 IF ERRN=56 THEN
1815   PRINTER IS 701
1820   CAT
1825   FOR Q=1 TO 5
1830     PRINT

```



```

1835     NEXT Q
1840     PRINTER IS 1
1845     END IF
1850     PRINT USING "@,@"
1855     BEEP
1860     PRINT ERRMSG
1865     GOTO Recall_data
1870 Store_data: !***** STORE_DATA *****
1875     GOSUB Which_menu
1880     ON ERROR GOTO Store_err
1885     INPUT "File to be used? Don't type suffix D,C,or-Z.",File_name$
1890     Xfile$=File_name$&"B"
1891     Yfile$=File_name$&"C"
1892     Zfile$=File_name$&"Z"
1893     Qfile$=File_name$&"Q"
1894     ASSIGN @Path1 TO Xfile$
1895     ASSIGN @Path2 TO Yfile$
1896     ASSIGN @Path3 TO Zfile$
1897     ASSIGN @Path4 TO Qfile$
1900     ON END @Path4 GOTO Main_menu
1909     OFF ERROR
1900     ON ERROR GOTO 1902
1901     OUTPUT @Path1;Strain(*)
1902     OFF ERROR
1903     ON ERROR GOTO 1905
1904     OUTPUT @Path2;Stress(*)
1905     OFF ERROR
1906     ON ERROR GOTO 1910
1907     E_c=Ex_convert
1908     E_i=Ex_inter
1909     OUTPUT @Path3;Sample_nr$,X_axis$,Y_axis$,Dia,Wide,Thick,Gauge,T_start,T_end,Load_min,Load_max,Fs_load_cell,Te_co,Str_rate,Extensometer$,E_c,E_i,Test_temp
1910     OFF ERROR
1911     ON ERROR GOTO 1914
1912     OUTPUT @Path4;Extens(*)
1913     OFF ERROR
1914     ASSIGN @Path4 TO *
1915     ASSIGN @Path1 TO *
1916     ASSIGN @Path2 TO *
1917     ASSIGN @Path3 TO *
2030     MASS STORAGE IS ":CS80,700,1"
2035     GOTO Main_menu
2040 Store_err: !***** STORE_ERR *****
2045     PRINTER IS 1
2050     IF ERRN=56 THEN
2055         OFF ERROR
2060         PRINT "File not found. Below is a list of current files."
2065         CAT
2070         FOR Q=1 TO 5
2075             PRINT
2080         NEXT Q

```

```

2085 PRINT "Would you like to create a new file?"
2090 GOSUB Yes_no
2095 IF Answer$="Y" THEN
2100 PRINT "Insert data disk"
2105 BEEP
2110 INPUT "File name?",File_name$
2115 New_file: !
2120 ON ERROR GOTO Disk_full
2125 PRINT "Creating new files....."
2130 CREATE BOAT File_name$&"D",8,5000
2135 CREATE BOAT File_name$&"C",8,5000
2140 CREATE BOAT File_name$&"Z",1,5000
2145 CREATE BOAT File_name$&"Q",1,5000
2150 OFF ERROR
2155 ELSE
2160 GOTO Store_data
2165 END IF
2170 ELSE
2175 PRINT ERRM$
2180 OFF ERROR
2185 PRINT "Do you want to try again?"
2190 GOSUB Yes_no
2195 IF Answer$="Y" THEN Store_data
2200 GOTO Main_menu
2205 ENO IF
2210 PRINT USING "@,@"
2215 BEEP
2220 GOTO Store_data
2225 Disk_full: !***** DISK_FULL *****
2230 OFF ERROR
2235 PRINT "This disk is full. Do you want to replace it with a new disk?"
2240 GOSUB Yes_no
2245 IF Answer$="N" THEN Store_data
2250 GOTO New_file
2255 Print_data: !***** PRINT_DATA *****
2260 PRINTER IS 701
2265 GOSUB Show_set_up_2
2270 PRINTER IS 1
2275 GOTO Main_menu
2280 Plot_data: !***** PLOT_DATA *****
2281 IF Old_axes=3 THEN GOSUB Plot_data_21 TO MAKE A SUPERIMPOSED PLOT
2282 IF Xx=2 THEN
2283 X_axis$="Engineering Strain"
2284 Y_axis$="Engineering Stress, MPa"
2285 ENO IF
2286 IF Xx=3 THEN
2287 X_axis$="True Strain"
2288 Y_axis$="True Stress, MPa"
2289 ENO IF
2290 GOSUB Plot_set_up
2291 L_type=0

```

```

2292 Next_curve: !
2293 L_type=L_type+1
2294 LINE TYPE L_type
2295 OFF KEY
2296 ON KEY 1 LABEL "ContinuePlot" GOTO Plot_data_2
2297 ON KEY 2 LABEL "CHANGE MAINAXES" GOTO Plot_axes
2298 ON KEY 3 LABEL "CHANGE SUB-AXES" GOTO Sub_axes
2299 ON KEY 3 LABEL " " " GOTO Sub_axes
2300 ON KEY 4 LABEL "NEW PLOT" GOTO Main_menu
2301 ON KEY 5 LABEL "Main Menu" GOTO Main_menu
2302 ON KEY 6 LABEL "Print Data" GOTO Print_data
2303 IF Extensometer$="ON" THEN
2304 ON KEY 7 LABEL "LOAD- TIME" GOTO Plot_data_2
2305 ELSE
2306 ON KEY 7 LABEL "Stress- Strain" GOTO Stress_strain
2307 END IF
2308 ON KEY 8 LABEL "REDUCE DATA" GOTO Data_red_menu
2309 KEY LABELS ON
2310 IF Xx=3 THEN PRINT "TRUE STRESS (MAX)=";Stress_max;" TRUE STRAIN (MAX)="
;Strain_max
2311 IF Xx=2 THEN PRINT "ENGR STRESS (MAX)=";Stress_max;" ENGR STRAIN (MAX)="
;Strain_max
2313 Plot_data_idle:GOTO Plot_data_idle
2314 Plot_axes: !..... PLOT_AXES .....
2315 GOSUB Axes_u
2316 GOSUB Start_t
2317 GOSUB Plot_set_up
2318 GOTO Plot_data_2
2319 Sub_axes: !..... SUB_AXES .....
2320 GOSUB Ex_plt_cnv
2321 GOSUB Plot_set_up
2322 GOTO Plot_data_2
2323 Plot_data_3: !..... PLOT_DATA_3 .....
2324 KEY LABELS OFF
2325 IF Answer$="Y" THEN GOSUB Pen_select
2326 FOR I=1 TO 5000
2327 Explot=Extens(I)*Exp_con+Exp_int
2328 IF I=1 OR Explot=T_start THEN MOVE Explot,Stress(I)
2329 IF Explot<T_start OR Explot>T_end THEN End_plot_3
2330 PLOT Explot,Stress(I)
2331 End_plot_3: !
2332 NEXT I
2333 IF Answer$="Y" THEN PEN 0
2334 GOTO Next_curve
2335 Re_data_1: !..... RE_DATA_1 .....
2336 GOSUB Re_data
2337 Plot_data_2: !..... PLOT_DATA_2 .....
2338 IF Which_pltr$="Plotter" THEN GOSUB Pen_select
2340 KEY LABELS OFF
2342 FOR I=1 TO 5000
2343 IF I=N_points THEN GOTO Next_curve

```

```

2345 IF I=1 OR Strain(I)=T_start THEN MOVE Strain(I),Stress(I)
2347 IF Strain(I)<T_start THEN End_curve
2348 IF Strain_engr(I)<T_start THEN End_curve
2349 IF Ie_co=1 AND (Stress(I)>Load_max OR Stress(I)<Load_min) THEN GOTO End_
curve
2350 IF Ie_co=3 AND (Stress(I)<Load_max OR Stress(I)>Load_min) THEN GOTO End_
curve
2351 IF Strain(I)>T_end OR Strain_engr(I)>T_end THEN
2352 I=5000
2353 GOTO End_curve
2354 END IF
2355 IF I>N_points AND Strain(I)=0 THEN
2356 GOTO Next_curve
2357 END IF
2359 IF Xx=0 OR Xx=3 THEN PLOT Strain(I),Stress(I)
2360 IF Xx=2 THEN PLOT Strain_engr(I),Stress_engr(I)
2361 End_curve: !
2362 NEXT I
2363 IF Answer$="Y" THEN PEN 0
2364 GOTO Next_curve
2365 Show_set_up_1: !***** SHOW_SET_UP_1 *****
2366 GOSUB Show_set_up
2367 GOTO Main_menu_idle
2368 Stopper: !***** STOPPER*****
2369 PRINTER IS 1
2370 KEY LABELS OFF
2371 PRINT "Do you want use this program again?"
2372 GOSUB Yes_no
2373 IF Answer$="N" THEN LOAD "MSLABS"
2374 IF Answer$="Y" THEN GOTO Starter
2376 STOP
2377 Load_cell: !***** LOAD_CELL *****
2378 KEY LABELS OFF
2379 INPUT "What is the full-scale load value in kN?",Fs_load_cell
2380 GOTO Main_menu
2381 S_area: 1
2382 OFF KEY
2383 FOR Q=1 TO 4
2384 ON KEY Q LABEL "round sample" GOTO Round
2385 ON KEY Q+4 LABEL "rect. sample" GOTO Rect
2386 NEXT Q
2387 KEY LABELS ON
2388 S_area_idle:GOTO S_area_idle
2389 Round:1
2390 KEY LABELS OFF
2391 INPUT "Sample diameter, mm?",Dia
2392 Sample_area=(PI/4)*(Dia^2)
2393 GOTO G_length
2394 Rect: 1
2395 KEY LABELS OFF
2396 INPUT "Sample width, mm?",Wide

```

```

2397 INPUT "Sample thickness, mm?", Thick
2398 Sample_area=Wide*Thick
2399 G_length:1
2400 PRINT "Default gauge length is ", Gauge, " mm. Hit <RETURN> to accept"
2401 INPUT "Gauge length, mm?", Gauge
2402 RETURN
2403 Show_set_up:1***** SHOW_SET_UP *****
2404 PRINTER IS 1
2405 Show_set_up_2:1***** SHOW_SET_UP_2 *****
2406 PRINT USING "0,#"
2407 PRINT "Current set up is as follows:"
2408 PRINT "    Sample Parameters:"
2409 IF Sample_nr$="" THEN
2410     PRINT "        Sample unnamed"
2411 ELSE
2412     PRINT "        Sample: "; Sample_nr$
2413 END IF
2414 IF Gauge<>0 THEN
2415     PRINT "        Gauge length is "; Gauge, " mm"
2416 ELSE
2417     PRINT "        No gauge length specified"
2418 END IF
2419 IF Dia<>0 THEN Sample_area=(PI/4)*(Dia^2)
2420 IF Thick<>0 AND Wide<>0 THEN Sample_area=Wide*Thick
2421 IF Sample_area<>0 THEN
2422     IF Dia<>0 THEN
2423         PRINT "        Using round sample with a diameter of "; Dia, " mm"
2424     ELSE
2425         PRINT "        Using flat sample "; Wide, " mm wide X "; Thick, " mm thick"
2426     END IF
2427     PRINT "        Sample area is "; Sample_area, " mm^2"
2428 ELSE
2429     PRINT "        Sample dimensions are incomplete"
2430 END IF
2431 PRINT
2432 PRINT "    Testing Parameters:"
2433 PRINT "        Crosshead speed"; Str_rate, " mm/min"
2434 PRINT "        Full-scale range of load cell is set for "; Fs_load_cell, " kN"
2435 PRINT "        Hold time at finish "; Hold_time, " min"
2436 IF Te_co=1 THEN PRINT "        Tension only test"
2437 IF Te_co=2 THEN PRINT "        Tension/compression test"
2438 IF Te_co=3 THEN PRINT "        Compression only test"
2439 PRINT "        Extensometer/Strain Gage is "; Extensometer$
2440 IF Extensometer$="On" THEN
2441     PRINT "        Extensometer/Strain gage conversion factor is "; Ex_convert
2442     PRINT "        Extensometer/Strain gage intercept is "; Ex_inter
2443     PRINT "        Strain shown will be from "; Explot0, " to "; Explotmax
2444 END IF
2445 PRINT "        Test temperature is "; Test_temp, " deg C or "; Test_temp+273.15,
" K"
2446 PRINT

```



```

2447 PRINT "    Plotting Parameters:"
2448 IF X_axis$="Time, minutes" THEN PRINT "        Start time ";T_start;" min    F
inish time ";T_end;" min"
2449 IF X_axis$="Time, seconds" THEN PRINT "        Start time ";T_start;" sec    F
inish time ";T_end;" sec"
2450 IF X_axis$="Elongation, mm" THEN PRINT "        Starting Elongation ",T_start
;" mm    Finish Elongation ";T_end;" mm"
2451 IF X_axis$="Elongation, Percent" THEN PRINT "        Starting Elongation ",T
start;" %    Finish Elongation ";T_end;" %"
2452 IF X_axis$="Strain" OR Xx=2 OR Xx=3 THEN PRINT "        Starting strain ",T_s
tart;" Finish strain ";T_end
2453 IF Y_axis$="Volts DC" THEN PRINT "        Y-axis minimum is ";Load_min;" volt
s    and Y-axis maximum is ";Load_max;" volts"
2454 IF Y_axis$="Millivolts DC" THEN PRINT "        Y-axis minimum is ";Load_min;"
millivolts    and Y-axis maximum is ";Load_max;" millivolts"
2455 IF Y_axis$="Load, kN" THEN PRINT "        Load ranges from ",Load_min;" kN to
";Load_max;" kN    (neg means compression)"
2456 IF Y_axis$="Stress, MPa" OR Xx=2 OR Xx=3 THEN
2457     PRINT "        Stress ranges from ",Load_min;" MPa to ";Load_max;" MPa"
2458     PRINT "        (neg means compression)"
2459 ENO IF
2460 RETURN
2461 Set_up_menu: !
2462 BEEP 2000,.2
2463 BEEP 2100,.2
2464 OFF KEY
2465 GOSUB Show_set_up
2466 ON KEY 1 LABEL "Sample  Params" GOTO Sample_id_s
2467 ON KEY 2 LABEL "Sample  Params" GOTO Sample_id_s
2468 ON KEY 3 LABEL "Test    Params" GOTO Test_params
2469 ON KEY 4 LABEL "Test    Params" GOTO Test_params
2470 ON KEY 5 LABEL "PlottingParams" GOTO Axes_units
2471 ON KEY 6 LABEL "PlottingParams" GOTO Axes_units
2472 ON KEY 7 LABEL "" GOTO Set_up_idle
2473 ON KEY 8 LABEL "SETUP   OK" GOTO Main_menu
2474 IF Sample_nr$="" THEN ON KEY 8 LABEL "IOENTIFYSAMPLE" GOTO Sample_id_s
2475 !SEE LINE 2455 *****
2476 IF (Y_axis$="Load, kN" OR Y_axis$="Stress, MPa" OR Xx=2 OR Xx=3) AND Fa_lo
ad_cell=0 THEN
2477     ON KEY 8 LABEL "NEED    LOACELL" GOTO Load_cell
2478     BEEP 2000,.1
2479 ENO IF
2480 IF ((Y_axis$="Stress, MPa" OR Xx=2 OR Xx=3) AND Sample_area=0) OR (X_axis$
="Elongation, %" OR X_axis$="Strain" OR Xx=2 OR Xx=3 AND Gauge=0) THEN
2481     ON KEY 8 LABEL "SAMPLE  OIMEN." GOTO S_area_2
2482 END IF
2483 IF (X_axis$="Elongation, mm" OR X_axis$="Elongation, %" OR X_axis$="Strain
" OR Xx=2 OR Xx=3) AND Str_rate=0 THEN
2484     ON KEY 7 LABEL "X-head  Speed" GOTO Rates
2485     ON KEY 8 LABEL "" GOTO Rates
2486 END IF

```

```

2487 KEY LABELS ON
2488 Sat_up_idle:GOTO Sat_up_idle
2489 Test_params: !***** TEST_PARAMS *****
2490 ON KEY 1 LABEL "Change X-head V" GOTO Rates
2491 ON KEY 2 LABEL "Change Load Cell" GOTO Load_cell
2492 ON KEY 3 LABEL "Tension/Compression" GOTO Tan_com
2493 ON KEY 4 LABEL "Hold Time" GOTO Holds
2494 ON KEY 5 LABEL "Extens. Toggle" GOTO Extoggle_1
2495 FOR Q=6 TO 8
2496   ON KEY Q LABEL "" GOTO Test_par_spin
2497 NEXT Q
2498 Test_par_spin:GOTO Test_par_spin
2499 Extoggle_1: !
2500 GOSUB Ex_toggle
2501 GOSUB Ex_cnv
2502 GOSUB Ex_plt_cnv
2503 GOTO Set_up_menu
2504 G_1_set_up: !
2505 Var=Gauge
2506 PRINT "Changing gauge length"
2507 GOSUB Var_change
2508 Gauge=Var
2509 GOTO Set_up_menu
2510 Start_t: !
2511 Var=T_start
2512 PRINT "Changing minimum x-axis value:"
2513 GOSUB Var_change
2514 T_start=Var
2515 Var=T_end
2516 PRINT "Changing maximum x-axis value:"
2517 GOSUB Var_change
2518 T_end=Var
2519 T_ran=T_end-T_start
2520 Load_vals: !
2521 Var=Load_min
2522 PRINT "Changing minimum y-axis value:"
2523 GOSUB Var_change
2524 Load_min=Var
2525 Var=Load_max
2526 PRINT "Changing maximum y-axis value:"
2527 GOSUB Var_change
2528 Load_max=Var
2529 Load_ran=Load_max-Load_min
2530 RETURN
2531 Axes_units: !***** AXES_UNITS *****
2532 GOSUB Axes_u
2533 GOSUB Start_t
2534 GOTO Set_up_menu
2535 Axes_u: !***** AXES_U *****
2536 KEY LABELS OFF
2537 OFF KEY

```

```

2538 PRINT "Select label for X-axis. Default is time in minutes"
2539 ON KEY 1 LABEL "Time    Minutes" GOTO Time_min
2540 ON KEY 2 LABEL "Time    Seconds" GOTO Time_sec
2541 ON KEY 3 LABEL "Elong.  mm" GOTO Elong_mm
2542 ON KEY 4 LABEL "Elong.  %" GOTO Elong_pct
2543 ON KEY 5 LABEL " True    Strain" GOTO Strain_axis
2544 ON KEY 6 LABEL " Engr    Strain" GOTO Strain_axis
2545 FOR Q=7 TO 8
2546     ON KEY Q LABEL "" GOTO Axes_idle
2547 NEXT Q
2548 KEY LABELS ON
2549 Axes_idle:GOTO Axes_idle
2550 Time_min:|
2551 X_axis$="Time, minutes"
2552 GOTO Set_up_y_axis
2553 Time_sec:|
2554 X_axis$="Time, seconds"
2555 GOTO Set_up_y_axis
2556 Elong_mm:|
2557 X_axis$="Elongation, mm"
2558 GOTO Set_up_y_axis
2559 Elong_pct:|
2560 X_axis$="Elongation, Percent"
2561 GOTO Set_up_y_axis
2562 Strain_axis:|
2563 X_axis$="Strain"
2564 IF Xx=2 THEN X_axis$="Engineering Strain"
2565 IF Xx=3 THEN X_axis$="True Strain"
2566 Set_up_y_axis:|
2567 OFF KEY
2568 PRINT "Select label for Y-axis. Default is load"
2569 ON KEY 3 LABEL "Volts    DC" GOTO Volts_y
2570 ON KEY 5 LABEL "mV      DC" GOTO Mv_y
2571 ON KEY 1 LABEL "Load, N" GOTO Load_y
2572 ON KEY 2 LABEL "T Stress  MPa " GOTO Stress_y
2573 ON KEY 3 LABEL "E Stress  MPa " GOTO Stress_y
2574 FOR Q=5 TO 8
2575     ON KEY Q LABEL "" GOTO Y_ax_idle
2576 NEXT Q
2577 KEY LABELS ON
2578 Y_ax_idle:GOTO Y_ax_idle
2579 Volts_y:|
2580 Y_axis$="Volts DC"
2581 RETURN
2582 Mv_y:|
2583 Y_axis$="Millivolts DC"
2584 RETURN
2585 Load_y:|
2586 Y_axis$="Load, kN"
2587 RETURN
2588 Stress_y:|

```

```

2509 IF Xx=2 THEN Y_axis$="Engr Stress MPa  "
2590 IF Xx=3 THEN Y_axis$="True Stress MPa  "
2591 RETURN
2592 Rates: !
2593 Var=Str_rate
2594 PRINT "Editing crosshead speed: give value in mm/min"
2595 GOSUB Var_change
2596 Str_rate=Var
2597 GOTO Set_up_menu
2598 Holds: !
2599 GOSUB Holds1
2600 GOTO Set_up_menu
2601 Holds1: !
2602 PRINT "Change hold time?"
2603 GOSUB Yes_no
2604 IF Answer$="Y" THEN
2605     Var=Hold_time
2606     GOSUB Var_change
2607     Hold_time=Var
2608 END IF
2609 RETURN
2610 Ex_toggle: !
2611 PRINT "Toggle extensometer?"
2612 GOSUB Yes_no
2613 IF Answer$="N" THEN GOTO Ex_cnv
2614 IF Extensometer$="Off" THEN
2615     Extensometer$="On"
2616 ELSE
2617     Extensometer$="Off"
2618 END IF
2619 RETURN
2620 Ex_cnv: !
2621 IF Extensometer$="On" THEN
2622     PRINT "Change conversion factor?"
2623     GOSUB Yes_no
2624     IF Answer$="Y" THEN
2625         Var=Ex_convert
2626         GOSUB Var_change
2627         Ex_convert=Var
2628     END IF
2629     PRINT "Change intercept?"
2630     GOSUB Yes_no
2631     IF Answer$="Y" THEN
2632         Var=Ex_inter
2633         GOSUB Var_change
2634         Ex_inter=Var
2635     END IF
2636 END IF
2637 RETURN
2638 Ex_plt_cnv: !
2639 IF Extensometer$="On" THEN

```

```

2640 PRINT "Change minimum strain plotted?"
2641 GOSUB Yes_no
2642 IF Answer$="Y" THEN
2643     Var=Explot0
2644     GOSUB Var_change
2645     Explot0=Var
2646 END IF
2647 PRINT "Change maximum strain plotted?"
2648 GOSUB Yes_no
2649 IF Answer$="Y" THEN
2650     Var=Explotmax
2651     GOSUB Var_change
2652     Explotmax=Var
2653 END IF
2654 Exp_con=(T_start-T_end)/(Explot0-Explotmax)
2655 Exp_int=T_start-Explot0*Exp_con
2656 END IF
2657 RETURN
2658 Ten_com: !
2659 KEY LABELS OFF
2660 PRINT "TENSION, TENSION/COMPRESSION OR COMPRESSION TEST?"
2661 BEEP 2000,.1
2662 OFF KEY
2663 ON KEY 1 LABEL "TENSION" GOTO Ten_only
2664 ON KEY 2 LABEL "TENSION" GOTO Ten_only
2665 ON KEY 3 LABEL "" GOTO Ten_idle
2666 ON KEY 4 LABEL "TENSION/COMPRESS" GOTO Ten_and_com
2667 ON KEY 5 LABEL "TENSION/COMPRESS" GOTO Ten_and_com
2668 ON KEY 6 LABEL "" GOTO Ten_idle
2669 ON KEY 7 LABEL "COMPRESS" GOTO Com_only
2670 ON KEY 8 LABEL "COMPRESS" GOTO Com_only
2671 KEY LABELS ON
2672 Ten_idle:GOTO Ten_idle
2673 Ten_only:Te_co=1
2674 GOTO Set_up_menu
2675 Ten_and_com:Te_co=2
2676 GOTO Set_up_menu
2677 Com_only:Te_co=3
2678 GOTO Set_up_menu
2679 Var_change:!
2680 INPUT "Type in desired value",Var
2681 PRINTER IS !
2682 PRINT Var;"Is this OK?"
2683 GOSUB Yes_no
2684 IF Answer$="N" THEN Var_change
2685 RETURN
2686 OFF KEY
2687 KEY LABELS ON
2688 ON KEY 1 LABEL "ADD 100" GOTO Hun_more!$$$$$$$$$$$$$$$$$ CHANGE LATER
2689 ON KEY 2 LABEL "ADD 10" GOTO Ten_more
2690 ON KEY 3 LABEL "ADD 1" GOTO One_more

```



```

2691 ON KEY 4 LABEL "OK" GOTO Var_return
2692 ON KEY 5 LABEL "SUBTRACT 1" GOTO One_less
2693 ON KEY 6 LABEL "MULTIPLYBY .1" GOTO Mult_pt_1
2694 ON KEY 7 LABEL "MULTIPLYBY 10" GOTO Mult_10
2695 ON KEY 8 LABEL "SET TO 0" GOTO Var_zero
2696 PRINTER IS 1
2697 PRINT "Current value is ";Var
2698 Var_idle:GOTO Var_idle
2699 Var_return:
2700 RETURN
2701 Var_zero:
2702 Var=0
2703 GOTO Var_change
2704 Hun_more:
2705 Var=Var+100
2706 GOTO Var_change
2707 Ten_more:
2708 Var=Var+10
2709 GOTO Var_change
2710 One_more:
2711 Var=Var+1
2712 GOTO Var_change
2713 Mult_pt_1:
2714 Var=Var*.10
2715 GOTO Var_change
2716 Mult_10:
2717 Var=Var*10
2718 GOTO Var_change
2719 One_less:
2720 Var=Var-1
2721 GOTO Var_change
2722 GOTO Set_up_menu
2723 Set_up_ok:1..... SET_UP_OK .....
2724 PRINT " "
2725 PRINT "DO YOU WISH TO:"
2726 PRINT " "
2727 PRINT "          RUN A TEST          OR          REDUCE DATA          ?"
2728 PRINT "          <YES>                  <NO>"
2729 GOSUB Yes_no
2730 IF Answer$="Y" THEN GOTO Init_daq
2731 IF Answer$="N" THEN GOSUB Plot_data
2740 Init_daq:
2742 CLEAR SCREEN
2743 PRINT " "
2744 PRINT "WHAT IS TIME FRAME FOR DATA COLLECTION (DURATION OF EXPERIMENT)?"
2745 PRINT " "
2746 OFF KEY
2747 ON KEY 1 LABEL " 15 MINUTES" GOTO Test_duration
2748 ON KEY 2 LABEL " HALF HOUR " GOTO Test_duration
2749 ON KEY 3 LABEL " ONE HOUR " GOTO Test_duration
2750 ON KEY 4 LABEL " TWO HOURS " GOTO Test_duration

```

```

2751 ON KEY 5 LABEL " FOUR      HOURS " GOTO Test_duration
2752 ON KEY 6 LABEL " EIGHT     HOURS " GOTO Test_duration
2753 ON KEY 7 LABEL " HALF      DAY " GOTO Test_duration
2754 ON KEY 8 LABEL " FULL      OAY " GOTO Test_duration
2755 KEY LABELS ON
2756 Runn_idl:GOTO Runn_idle
2757 Test_duration: 1          FEED THIS LATER TO SET UP NUMBER,
2758 KEY LABELS OFF           AND FREQUENCY OF DATA POINTS
2760 GOSUB Plot_set_up!      AND FREQUENCY OF DATA COLLECTION
2761 OUTPUT 709;"CLR"
2762 OUTPUT 709;"USE 000"
2763 PRINTER IS 1
2764 Re_test: 1
2765 Acq_data:1***** ACQ_DATA *****
2766 IF Which_pltr$="CRT" THEN
2767   Penn$="Data"
2768   GOSUB Pen_select
2769 END IF
2770 FOR Q=1 TO 4
2771   ON KEY Q LABEL "TEST    COMPLETE" GOTO Test_done
2772   ON KEY Q+4 LABEL "RE-STARTTEST" GOTO Re_test
2773 NEXT Q
2774 KEY LABELS ON
2775 T_total=T_end-T_start
2776 T_convert=1 !assumes x-axis is in seconds
2777 IF X_axis$="Time, minutes" THEN T_convert=1/60
2778 IF X_axis$="Elongation, mm" THEN T_convert=Str_rate/60
2779 IF X_axis$="Elongation, %" THEN T_convert=(Str_rate/Gauge)*(100/60)
2780 IF X_axis$="Strain" THEN T_convert=(Str_rate/60)/Gauge
2781 IF X_axis$="Engineering Strain" THEN T_convert=(Str_rate/60)/Gauge
2782 IF X_axis$="True Strain" THEN T_convert=(Str_rate/60)/Gauge
2783 L_convert=1 !assumes DCV is output
2784 IF Y_axis$="Millivolts OC" THEN L_convert=1000
2785 IF Y_axis$="Load, kN" THEN L_convert=Fs_load_cell/10
2786 IF Y_axis$="Stress, MPa" THEN L_convert=(Fs_load_cell*100)/Sample_area
2787 IF Y_axis$="Engr Stress MPa " THEN L_convert=(Fs_load_cell*100)/Sample_
area
2788 IF Y_axis$="True Stress MPa " THEN L_convert=(Fs_load_cell*100)/Sample_
area
2789 KEY LABELS OFF
2790 INPUT "Hit <RETURN> when ready to proceed.",Which$
2791 KEY LABELS ON
2792 T_0=TIMEDATE !Time is measured in seconds then converted to desired unit
2793 LONG S
2794 FOR I=0 TO 5000
2795   REPEAT
2796     T_i=(TIMEDATE-T_0)*T_convert
2797     UNTIL T_i>=(T_total/5000)*(I)
2798     Strain(I)=T_i
2799     OUTPUT 709;"CONFMEAS DCV,214"
2800     ENTER 709;Stress(I)

```

```

2801 Stress(I)=Stress(I)*L_convert
2802 PLOT Strain(I),Stress(I)
2803 IF Extensometer$="On" THEN
2804     OUTPUT 709;"CONFMEAS DCV,215"
2805     ENTER 709;Extens(I)
2806     Extens(I)=Extens(I)*Ex_convert/Ex_inter:CONVERTS TO STRAIN VALUES
2807     Exploit=Extens(I)*Exp_convert/Exp_intl:CONVERTS STRAIN TO PLOTABLE VALUES
2808     MOVE Exploit,Stress(I)
2809     LABEL USING "K";"."
2810 END IF
2811 NEXT I
2812 Test_done: !
2813 N_points=I
2815 OFF KEY
2816 FOR Q=1 TO 4
2817     ON KEY Q LABEL " " " GOTO Dumper
2818     ON KEY Q+4 LABEL "Main Menu" GOTO Main_menu
2819 NEXT Q
2820 T_d_idle:GOTO T_d_idle
2821 Pen_select: !
2822 ON KEY 1 LABEL "Pen 1" GOTO P1
2823 ON KEY 2 LABEL "Pen 2" GOTO P2
2824 ON KEY 3 LABEL "Pen 3" GOTO P3
2825 ON KEY 4 LABEL "Pen 4" GOTO P4
2826 ON KEY 5 LABEL "Pen 5" GOTO P5
2827 ON KEY 6 LABEL "Pen 6" GOTO P6
2828 ON KEY 7 LABEL "Drawing "&Penn$ GOTO Pen_select_idle
2829 ON KEY 8 LABEL "Drawing "&Penn$ GOTO Pen_select_idle
2830 KEY LABELS ON
2831 BEEP 2000,.1
2832 Pen_select_idle:GOTO Pen_select_idle
2833 P1:PEN 1
2834 GOTO Pen_return
2835 2:PEN 2
2836 GOTO Pen_return
2837 3:PEN 3
2838 GOTO Pen_return
2839 P4:PEN 4
2840 GOTO Pen_return
2841 P5:PEN 5
2842 GOTO Pen_return
2843 P6:PEN 6
2844 Pen_return: !
2845 KEY LABELS OFF
2846 RETURN
2847 Dumper: !***** DUMPER *****
2848 KEY LABELS OFF
2849 OUMP OEVICE IS 701
2850 OUTPUT KBD;"N";
2851 GOTO Main_menu

```

```

2879 File_err: !***** FILE_ERR *****
2880 PRINTER IS 1
2881 PRINT USING "0,#"
2882 DECF 2000,.3
2883 IF ERRN=70 OR ERRN=05 THEN
2884   PRINT "WARNING you are initializing this disc. All data will be erased.
2885   INPUT "Hit <RETURN> to continue",Which$
2886   INITIALIZE ":CS80,700,1"
2887 END IF
2888 PRINT "Error in file name selection",ERRN,ERRMS
2889 GOTO Data_save
2890 Plot_set_up: !***** PLOT_SET_UP *****
2891 PRINTER IS 1
2892 OFF KEY
2893 PRINT "Do you want to use the Plotter?"
2894 GOSUB Yes_no
2895 OUTPUT KBD;"K";
2896 IF Answer$="Y" THEN INPUT "Put paper in the plotter then hit <RETURN>",Whi
ch$
2897 GINIT
2898 GRAPHICS ON
2899 IF Answer$="Y" THEN
2900   PLOTTER IS 705,"HPGL"
2901   VIEWPORT 0,125,0,100
2902   Which_pltr$="Plotter"
2903   Penn$="Axes"
2904   GOSUB Pen_select
2905 ELSE
2906   PLOTTER IS CRT,"INTERNAL"
2907   Which_pltr$="CRT"
2908   VIEWPORT 0,120,26,100
2909 END IF
2910 Load_ran=Load_max-Load_min
2911 T_ran=T_end-T_start
2912 WINDOW T_start-.1*(T_ran),T_end,Load_min-.1*Load_ran,Load_max+.13*Load_ran
2913 CLIP T_start,T_end,Load_min,Load_max
2914 GRID T_ran/10,Load_ran/10,T_start,Load_min,1,1
2915 CLIP OFF

```

```

2916 CSIZE 3
2917 LORG 4
2918 MOVE (T_start+T_end)/2,Load_max+.00*Load_ran
2919 LABEL USING "K";Sample_nr$&" "&VAL$(Test_temp)&" C"
2920 LORG 6
2921 FOR I=T_start TO T_end STEP (T_start-T_end)/(-5)
2922     MOVE I,Load_min-.025*Load_ran
2923     LABEL USING "K";I
2924 NEXT I
2925 MOVE .5*(T_start+T_end),Load_min-.07*Load_ran
2926 LABEL USING "K";X_axis$
2927 LORG 8
2928 FOR I=Load_min TO Load_max STEP Load_ran/10
2929     MOVE T_start-(.01*(T_start-T_start)),I
2930     LABEL USING "K";I
2931 NEXT I
2932 LORG 4
2933 MOVE T_start-(.07*(T_end-T_start)),Load_ran/2+Load_min
2934 DEG
2935 LDIR 90
2936 LABEL USING "K";Y_axis$
2937 LDIR 0
2938 LORG 4
2939 IF Extensometer$="On" THEN
2940     Exp_ran=Exploimax-Exploim0
2941     CLIP T_start+.1*T_ran,T_end,Load_max,Load_max+.1*Load_ran
2942     AXES T_ran/10,Load_ran/20,T_start,Load_max
2943     CLIP OFF
2944     FOR I=T_start TO T_end STEP T_ran/10
2945         MOVE I,Load_max+Load_ran*.03
2946         LABEL USING "K";(I-Exp_int)/Exp_con
2947     NEXT I
2948 END IF
2949 RETURN
2950 Which_msu: !***** WHICH_MSU *****
2951 OFF KEY
2952 MASS STORAGE IS ":CS80,700,0"!          HARD DRIVE FOR 2732A25753
2953 !                                          OR FLOPPY FOR 2702A21048
2954 CLEAR SCREEN
2955 PRINT "Do you want to store/recall data to/from the HARD DRIVE or 3-1/2 FL
OPPY?"
2956 PRINT " "
2957 PRINT "***<YES>   FOR HARD DRIVE          <NO> FOR FLOPPY*****"
2958 GOSUB Yes_no
2959 IF Answer$="Y" THEN GOTO Hard_msu
2960 CLEAR SCREEN
2961 PRINT "Which IIP system are you using?          (CODES ARE MACHINE DEPENDENT)"
2962 PRINT " "
2963 PRINT "***<YES> IF MSU #1 IN THE INSTRON ROOM,          <NO> FOR MSU #2*****"
2964 PRINT "          (SERIAL # 2732A25753)          (SERIAL # 2702A21048)
"

```



```

2879 File_err: !***** FILE_ERR *****
2880 PRINTER IS 1
2881 PRINT USING "0,%"
2882 BEEP 2000,.3
2883 IF ERRN=78 OR ERRN=85 THEN
2884   PRINT "WARNING you are initializing this disc. All data will be erased.
"
2885   INPUT "Hit <RETURN> to continue",Which0
2886   INITIALIZE "C500,700,1"
2887 END IF
2888 PRINT "Error in file name selection",ERRN,ERRM$
2889 GOTO Data_save
2890 Plot_set_up: !***** PLOT_SET_UP *****
2891 PRINTER IS 1
2892 OFF KEY
2893 PRINT "Do you want to use the Plotter?"
2894 GOSUB Yes_no
2895 OUTPUT KBO;"K";
2896 IF Answer$="Y" THEN INPUT "Put paper in the plotter then hit <RETURN>",Whi
ch$
2897 GINIT
2898 GRAPHICS ON
2899 IF Answer$="Y" THEN
2900   PLOTTER IS 705,"HPGL"
2901   VIEWPORT 0,125,0,100
2902   Which_pltr$="Plotter"
2903   Penn$="Axes"
2904   GOSUB Pen_select
2905 ELSE
2906   PLOTTER IS CRT,"INTERNAL"
2907   Which_pltr$="CRT"
2908   VIEWPORT 0,120,26,100
2909 END IF
2910 Load_ran=Load_max-Load_min
2911 T_ran=T_end-T_start
2912 WINDOW T_start-.1*(T_ran),T_end,Load_min-.1*Load_ran,Load_max+.13*Load_ran
2913 CLIP T_start,T_end,Load_min,Load_max
2914 GRID T_ran/10,Load_ran/10,T_start,Load_min,1,1
2915 CLIP OFF
2916 CSIZE 3
2917 LORG 4
2918 MOVE (T_start+T_end)/2,Load_max+.08*Load_ran
2919 LABEL USING "K";Sample_nr$&" "&VAL$(Test_temp)&" C"
2920 LORG 6
2921 FOR I=T_start TO T_end STEP (T_start-T_end)/(-5)
2922   MOVE I,Load_min-.025*Load_ran
2923   LABEL USING "K";I
2924 NEXT I
2925 MOVE .5*(T_start+T_end),Load_min-.07*Load_ran
2926 LABEL USING "K";X_axis$
2927 LORG 8

```

```

2928 FOR I=Load_min TO Load_max STEP Load_ran/10
2929     MOVE T_start-(.01*(T_end-T_start)),I
2930     LABEL USING "K";I
2931 NEXT I
2932 LORG 4
2933 MOVE T_start-(.07*(T_end-T_start)),Load_ran/2+Load_min
2934 OEG
2935 LOIR 90
2936 LABEL USING "K";Y_axis$
2937 LOIR 0
2938 LORG 4
2939 IF Extensometer#="On" THEN
2940     Exp_ran=Exploitmax-Exploit0
2941     CLIP T_start+.1*T_ran,T_end,Load_max,Load_max+.1*Load_ran
2942     AXES T_ran/10,Load_ran/20,T_start,Load_max
2943     CLIP OFF
2944     FOR I=T_start TO T_end STEP T_ran/10
2945         MOVE I,Load_max+Load_ran*.03
2946         LABEL USING "K";(I-Exp_int)/Exp_con
2947     NEXT I
2948 ENO IF
2949 RETURN
2950 Which_msu: !***** WHICH_MSU *****
2951 OFF KEY
2952 MASS STORAGE IS ":CS80,700,0"!          HARO ORIVE FOR 2732A25753
2953 !                                          OR FLOPPY FOR 2702A21048
2954 CLEAR SCREEN
2955 PRINT "Do you want to store/recall data to/from the HARO ORIVE or 3-1/2 FL
OPPY?"
2956 PRINT " "
2957 PRINT "***<YES>    FOR HARD ORIVE                <NO> FOR FLOPPY*****"
2958 GOSUB Yes_no
2959 IF Answer$="Y" THEN GOTO Hard_msu
2960 CLEAR SCREEN
2961 PRINT "Which HP system are you using?          (CODES ARE MACHINE DEPENDENT)"
2962 PRINT " "
2963 PRINT "***<YES> IF MSU #1 IN THE INSTRON ROOM,    <NO> FOR MSU #2*****"
2964 PRINT "          (SERIAL # 2732A25753)          (SERIAL # 2702A21048)"
2965 GOSUB Yes_no
2966 IF Answer$="Y" THEN MASS STORAGE IS ":CS80,700,0"
2967 IF Answer$="N" THEN MASS STORAGE IS ":CS80,700,1"
2968 KEY LABELS OFF
2969 RETURN
2970 Hard_msu: !
2971 CLEAR SCREEN
2972 PRINT "Which HP system are you using?          (CODES ARE MACHINE DEPENDENT)"
2973 PRINT " "
2974 PRINT "***<YES> IF MSU #1 IN THE INSTRON ROOM,    <NO> FOR MSU #2*****"
2975 GOSUB Yes_no
2976 IF Answer$="Y" THEN MASS STORAGE IS ":CS80,700,1"

```

```

2977 IF Answer$="N" THEN MASS STORAGE IS ":C500,700,0"
2978 KEY LABELS OFF
2979 RETURN
2980 Yes_no! 1
2981 OFF KEY
2982 KEY LABELS OFF
2983 FOR Q=1 TO 4
2984     ON KEY Q LABEL "YES" GOTO Yess
2985     ON KEY Q+4 LABEL "NO" GOTO Noo
2986 NEXT Q
2987 KEY LABELS ON
2988 Yes_no_idle:GOTO Yes_no_idle
2989 Yess:Answer$="Y"
2990 RETURN
2991 Noo:Answer$="N"
2992 RETURN
2993 Analyze_data: 1
2994 PRINTER IS 1
2995 PRINT "Data analysis section not written yet"
2996 BEEP
2997 GOTO Main_menu
2998 Data_red_menu: 1
2999 ! THIS SECTION IS FOR MAKING A "CORRECTED" TRUE/ENGR STRESS-
3000 ! STRAIN CURVES ----- DATA REDUCTION -----
3001 OFF KEY
3002 ON KEY 1 LABEL " INPUT      TYPE " GOTO Input_type!
3003 ON KEY 2 LABEL " SLOPE      OKAY? " GOTO Slope_ok!
3004 ON KEY 3 LABEL " PLOT      ENGR " GOTO Corr_engr!
3005 ON KEY 4 LABEL " PLOT      TRUE " GOTO Corr_true!
3006 ON KEY 5 LABEL " FILE      OATA " GOTO Oata_save2!
3007 ON KEY 6 LABEL " MORE      CURVES?" GOTO More_plots!
3008 ON KEY 7 LABEL " MAIN      MENU " GOTO Main_menu!
3009 ON KEY 8 LABEL " MAIN      MENU " GOTO Main_menu!
3010 KEY LABELS ON
3011 Data_red_idle:GOTO Data_red_idle
3012 Slope_ok:1***** SLOPE_OK *****
3013 GOSUB Yes_no
3014 IF Answer$="Y" THEN GOTO Data_red_menu!CHANGE TO CORR_ENGR???
3015 IF Answer$="N" THEN GOSUB Plot_data
3016 Input_type:1***** INPUT_TYPE *****
3017 PRINTER IS 1
3018 PRINT "Select method of designating the points to calculate the slope"
3019 ON KEY 1 LABEL "Mouse" GOTO Mouse_pts 1
3020 ON KEY 2 LABEL "Mouse" GOTO Mouse_pts!
3021 ON KEY 3 LABEL "Cursor Keys" GOTO Cursor_pts!
3022 ON KEY 4 LABEL "Cursor Keys" GOTO Cursor_pts!
3023 ON KEY 5 LABEL "X-Y      inputs" GOTO Xy_pts!
3024 ON KEY 6 LABEL "X-Y      inputs" GOTO Xy_pts!
3025 ON KEY 7 LABEL "OTHER" GOTO Cursor_pts!
3026 ON KEY 8 LABEL "OTHER" GOTO Cursor_pts!
3027 Desig_idle:GOTO Desig_idle

```

```

3028 Mouse_pts:| Uses Mouse to designate points to calculate slope
3029 | Fill in lines to use Mouse later
3030 GOTO Solve_slope
3031 Cursor_pts:| Uses Cursor to designate points to calculate slope
3032 KEY LABELS OFF
3033 TRACK 3 IS ON| initializes cursor routine
3034 GRAPHICS INPUT IS KBD,"ARROW KEYS"| specifies the input device
3035 SET LOCATOR Scale_c,(Hi_y+Low_y)/2| initializes location of cursor
3036 FOR Q=1 TO 4
3037     ON KEY Q LABEL "Point 1 Baseline" GOTO Locator_spin
3038     ON KEY Q+4 LABEL "<RETURN>when loc" GOTO Locator_spin
3039 NEXT Q
3040 KEY LABELS ON
3041 Locator_spin: |
3042     LOG 5
3043     DIGITIZE T1,L1| location of cursor when <RETURN> pressed
3044     MOVE T1,L1| places "*" on location & beeps to let you
3045     LABEL USING "K";"*"
3046     BEEP 2000,.1
3047     FOR Q=1 TO 4
3048         ON KEY Q LABEL "Point 2 Baseline" GOTO Locator_spin2
3049         ON KEY Q+4 LABEL "<RETURN>when loc" GOTO Locator_spin2
3050     NEXT Q
3051     KEY LABELS ON
3052 Locator_spin2: |
3053     LOG 5
3054     DIGITIZE T2,L2| location of cursor when <RETURN> pressed
3055     MOVE T2,L2| places "@" on location & beeps to let you
3056     LABEL USING "K";"@ "
3057     BEEP 2000,.2
3058     BEEP 2000,.1
3059     FOR Q=1 TO 4
3060         ON KEY Q LABEL "CUTOFF POINT " GOTO Locator_spin3
3061         ON KEY Q+4 LABEL "<RETURN>when loc" GOTO Locator_spin3
3062     NEXT Q
3063     KEY LABELS ON
3064 Locator_spin3: |
3065     LOG 5
3066     DIGITIZE T9,L9| THIS IS END OF GOOD DATA
3067     MOVE T9,L9
3068     LABEL USING "K";"# "
3069     BEEP 2000,.2
3070     BEEP 2000,.1
3071     GOTO Slope_solve
3072 Xy_pts:| Uses TIME-LOAD data to designate points to calculate slope
3073 INPUT "WHAT IS COORD FOR FIRST POINT (X1,Y1)?",T1,L1
3074 INPUT "WHAT IS COORD FOR 2nd POINT (X2,Y2)?",T2,L2
3075 INPUT "WHAT IS LAST GOOD DATA POINT (JUST THE TIME ONLY)?",T9
3076 GOTO Slope_solve
3077 Slope_solve:| Solves eqn of line  $y=Mx+b$ ;  $y \rightarrow$  LOAD  $x \rightarrow$  Time
3078 Slope=(L2-L1)/(T2-T1)| Solves for slope M
3079 P0=L2-(Slope*T2)| Solves for y-intercept

```

```

3080 T0=-P0/Slope!           Solves for X-intercept
3081 I  Y  =  M    (X)  +  B
3082 I  P  =  SLOPE (TIME) + P0
3083 GOTO Slope_draw
3084 Slope_draw: I Draws line y=Mx+b on top of LOAD-TIME curve
3085 LINE TYPE 1
3086 MOVE T0,0
3087 LONG 5
3088 LABEL USING "K","*"
3089 DRAW T0,0
3090 DRAW ((1.5*L2-P0)/Slope),1.5*L2
3091 LINE TYPE 1
3092 GOTO Data_red_menu
3093 Corr_engr: I ***** CORR_ENGR *****
3094 PRINT "Do you want an TRUE or ENGR stress vs strain plot?"
3095 PRINT "***<YES>  FOR TRUE STRESS/STRAIN          <NO> ENGR STRESS/STRAIN"
3096 GOSUB Yes_no
3097 IF Answer$="Y" THEN GOTO Corr_true
3098 Ee=2
3099 GOTO Flag_engr!
3100 BEEP
3101 Corr_true: I ***** CORR_TRUE *****
3102 Xx=3!           THIS MEANS TRUE STRESS/STRAIN AXES LABELS TO PLOT
3103 Ee=3
3104 Flag_engr: I
3105 IF Ee=2 THEN Xx=2!   THIS MEANS ENGR STRESS/STRAIN AXES LABELS TO PLOT
3106 Xhead_spd=Str_rate
3107 BEEP
3108 PRINT " "
3109 PRINT "          CALCULATIONS IN PROGRESS - PLEASE WAIT FOR BEEP!!"
3110 Tel=0
3111 Delta_time=0
3112 Displ=0
3113 Strain_max=0
3114 Stress_max=0
3115 Tt0=INT(T0)
3116 FOR I=Tt0 TO 5000!           PRIOR TO T0 WILL BE ZEROS
3117   Tp=Strain(I)
3118   Pp=Stress(I)
3119   IF Tp>T9 THEN GOTO Flag_one!   END OF GOOD DATA
3120   Tel=(Pp-P0)/Slope
3121   Delta_time=Tp-Tel
3122   Displ=Delta_time*Xhead_spd
3123   Stress_engr(I)=(1000*Pp)/Sample_area!   KILO TO CHANGE KN TO MPa
3124   Strain_engr(I)=Displ/Gauge
3125   IF Strain_engr(I)>Strain_max THEN Strain_max=Strain_engr(I)
3126   IF Stress_engr(I)>Stress_max THEN Stress_max=Stress_engr(I)
3127   Stress(I)=Stress_engr(I)*(1+Strain_engr(I))!   THIS IS REALLY
3128   Strain(I)=LOG(1+Strain_engr(I))!   TRUE STRESS & STRAIN
3129   IF Strain(I)<0 THEN Strain(I)=0

```



```

3131     IIF Strain(I)>Strain_max THEN Strain_max=Strain(I)
3132     IIF Stress(I)>Stress_max THEN Stress_max=Stress(I)
3133     Zz=I
3134     Zzz=5000-Zz
3135     IF Zzz=5000 OR Zzz=4000 OR Zzz=3000 OR Zzz=2000 OR Zzz=1000 THEN
3136     PRINT Zzz1                                COUNT DOWN - TELLS HOW LONG UNTIL DONE
3137     END IF
3138     NEXT I
3139     Zzz7=71                                     TELLS THE MAX VALUE FOR AXES
3140     !!eq_one: 1
3141     NEFP
3142     !T_end=Strain_max*1.2                         GIVES STRANGE
3143     !Load_max=Stress_max*1.2                     UNITS ON AXES
3144     GOSUB Plot_data
3145     PRINT " DO YOU WISH TO SAVE THIS PLOT EITHER ON DISK OR HARD DRIVE?"
3146     PRINT "                                <YES>                                <NO>"
3147     GOTO Yes_no
3148     IF Answer$="Y" THEN GOSUB Oata_save2
3149     More_plots: 1
3150     PRINT " DO YOU WISH TO ANOTHER PLOT SUPERIMPOSED ON THIS PL_?"
3151     PRINT "                                -----"
3152     PRINT "                                <YES>                                <NO>"
3153     GOTO Yes_no
3154     IF Answer$="Y" THEN
3155         Old_axes=3! *****USE SAME AXES WHEN PLOTTING
3156         GOSUB Re_data
3157         GOSUB Plot_data_2
3158     END IF
3159     PRINT " DO YOU WISH TO A SEPERATE, NEW PLOT?"
3160     PRINT "                                -----"
3161     PRINT "                                <YES>                                <NO>"
3162     GOTO Yes_no
3163     IF Answer$="Y" THEN
3164         Old_axes=2! *****USE NEW AXES WHEN PLOTTING
3165         GOSUB Plot_data
3166     END IF
3167     IF Answer$="N" THEN GOTO Oata_red_menu
3168     Data_save2: 1***** DATA_SAVE2 .. *****
3169     GOSUB Which_msu
3170     OFF KEY
3171     ON KEY 1 LABEL "STORE      DATA" GOTO Oata_save2_1
3172     FOR Q=2 TO 7
3173         ON KEY Q LABEL " " GOTO Data_save2_idle
3174     NEXT Q
3175     ON KEY 8 LABEL "MAIN      MENU" GOTO Main_menu
3176     KEY LABELS ON
3177     Oata_save2_idle:GOTO Data_save2_idle
3178     Oata_save2_1: 1*****DATA_SAVE2_1 *****
3179     !INPUT "File to be used? Don't type suffix B,C,orZ.",File_names$
3180     ON ERROR GOTO File_err

```

```

3101 777-77*16
3102 |      NEED TO MAKE THIS FILE THE ENGR AND TRUE ALSO
3103 CREATE BOAT "E1",1,50001      FILE FOR ENGR STRESS/STRAIN
3104 CREATE BOAT "E2",1,50001      CHANGE FROM "E2" TO FILENAME&E2
3105 ASSIGN @Path1 TO "E1"
3106 ASSIGN @Path2 TO "E2"
3107 OUTPUT @Path1;Strain_engr(*)|      IT GETS STUCK HERE
3108 OUTPUT @Path2;Stress_engr(*)
3109 ASSIGN @Path1 TO *
3110 ASSIGN @Path2 TO *
3111 CREATE BOAT "T1",1,50001      FILE FOR TRUE STRESS/STRAIN
3112 CREATE BOAT "T2",1,50001      THIS WAS ADDED IN LATER?!!
3113 ASSIGN @Path1 TO "T1"!      IT SAVED A T1 FILE!!!!!!
3114 ASSIGN @Path2 TO "T2"
3115 OUTPUT @Path1;Strain(*)
3116 OUTPUT @Path2;Stress(*)
3117 ASSIGN @Path1 TO *
3118 ASSIGN @Path2 TO *
3119 OFF ERROR
3200 GOTO Data_red_menu
3201 END
3202 SUB Changer(Ara(*),I)|***** CHANGER *****
3203   FOR I=1 TO 5000
3204     Ara(I)=Ara(I)*F
3205   NEXT I

```

APPENDIX B. TRUE STRESS VS. TRUE STRAIN CURVE




Figure 25. True stress vs. true strain, sample A, 10 vol. pct. Alumina, 400°C

APPENDIX C. DUCTILITY VS. TEMPERATURE CURVES




Figure 26. Ductility vs. temperature, sample A, 10 vol. pct. Alumina.

AL6061 15% ALUMINA 350A/250R
DUCTILITY OF SAMPLE C




Figure 27. Ductility vs. temperature, sample C, 15 vol. pct. Alumina.

AL6061 10% ALUMINA 350A/350R
DUCTILITY OF SAMPLE F




Figure 28. Ductility vs. temperature, sample F, 10 vol. pct. Alumina.

AL6061 15% ALUMINA 350A/350R
DUCTILITY OF SAMPLE G




Figure 29. Ductility vs. temperature, sample G, 15 vol. pct. Alumina.

AL6061 10% ALUMINA 350A/350R

DUCTILITY OF SAMPLE F




Figure 30. Ductility vs. temperature, sample F, 10 vol. pct. Alumina.

AL6061 15% ALUMINA 350A/350R

DUCTILITY OF SAMPLE G




Figure 31. Ductility vs. temperature, sample G, 15 vol. pct. Alumina.

APPENDIX D. ULTIMATE STRENGTH VS. TEMPERATURE CURVES




Figure 32. Ultimate strength vs. temperature, sample A, 10 vol. pct. Alumina.

AL6061 15% ALUMINA 350A/250R
UTS SAMPLE C




Figure 33. Ultimate strength vs. temperature, sample C, 15 vol. pct. Alumina.

AL6061 10% ALUMINA 350A/350R
UTS SAMPLE F




Figure 34. Ultimate strength vs. temperature, sample F, 10 vol. pct. Alumina.

AL6061 15% ALUMINA 350A/350R
UTS SAMPLE G




Figure 35. Ultimate strength vs. temperature, sample G, 15 vol. pct. Alumina.

AL6061 10% ALUMINA 350A/350R
UTS SAMPLE F




Figure 36. Ultimate strength vs. temperature, sample F, 10 vol. pct. Alumina.

AL6061 15% ALUMINA 350A/350R

UTS SAMPLE G




Figure 37. Ultimate strength vs. temperature, sample G, 15 vol. pct. Alumina.

LIST OF REFERENCES

1. Friend, C.M., "Impact Response of Short δ -Alumina Fibre/Aluminum Alloy Metal Matrix Composites", *Journal of Materials Science*, v. 23, p. 1967, June, 1988.
2. Askeland, D.R., *The Science and Engineering of Materials*, 2nd Ed., p. 571, PWS-KENT Publishing Company, 1989.
3. Schaefer, T.A., *Thermomechanical Processing and Ambient Temperature Properties of a 6061 Aluminum 10 Volume Percent Alumina Metal Matrix Composite*, Master's Thesis, Naval Postgraduate School, Monterey, California, March 1990.
4. Hunt, M., "Automotive MMC's: Better and Cheaper", *Materials Engineering*, v. 106, No. 10, pp. 45-48, October 1989.
5. Stephens, J.J., "Cast AL-7 Si Composites: Effect of Particle Type and Size on Microstructure", *Scripta Metallurgica*, v. 22, p. 1307, Aug 1988.
6. *Metals Handbook*, 9th ed., v. 1, American Society for Metals, 1978.
7. King, F., *Aluminum and Its Alloys*, p. 114, Ellis Horwood Limited, 1987.
8. Harris, S.J., "Development in Particulate and Short Fibre Composites", p. 4-1, AGARD Lecture Series No. 174, New Light Alloys, Monterey, California, 29-30 October 1990.
9. Cornie, J.A., "Processing of Metal and Ceramic Matrix Composites", p. 37, *Ceramic Bulletin*, v. 65, No. 2, 1986.
10. McCoy, J.W., Jones, C., and Wawner, F.E., "Preparation and Properties of Cast Ceramic/Aluminum Composites", p. 37, *SAMPE Quarterly*, January 1988.

11. Baetz, J.G., "Metal Matrix Material Definition and Characterization for Advanced Technical Missiles", p.123, Defense Technical Information Center, Alexandria, Virginia, 31 August 1983.
12. Riely, W., "Comparison of Astro-Quartz and Metal Matrix Composites for Laser Hardening of Satellites", p.4, Defense Technical Information Center, Alexandria, Virginia, May 1984.
13. Magill, M., *An Investigation of the Properties of Aluminum 6061 Composite of 10 and 15 Percent Alumina*, Master's of Science Thesis, Naval Postgraduate School, Monterey, California, June 1990.
14. Taylor, D., *The Effect of Lithium Content on the Creep of Lithium Containing Alloys*, Master's of Science Thesis, Naval Postgraduate School, Monterey, California, June 1989.
15. *Metals Handbook*, 8th ed., v. 8., p.124, American Society for Metals, 1973.
16. McDaniels, D.L., "Microstructure and Orientation Effects on Properties of Discontinuous Silicon Carbide/Aluminum Composites", NASA Technical Paper 2302, p. 4, Washington D.C., July 1984.
17. Humphreys, F.J., "Deformation and Annealing Mechanisms in Discontinuously Reinforced Metal Matrix Composites", 9th Riso Int. Symposium on Metallic and Ceramic Composites (ed. S.I. Anderson et al), pp.479-484, Riso National Laboratory, 1988.
18. Kellogg, T., Program Instron 6027, Lab Technician, Naval Post Graduate School, June 1989, Monterey, Ca.

INITIAL DISTRIBUTION LIST

	No. Copies
1. Library, Code 52 Naval Postgraduate School Monterey, CA 93943-5002	2
2. Defense Technical Information Center Cameron Station Alexandria, VA 93943-5000	2
3. Chairman, Code ME/Hy Mechanical Engineering Department Naval Postgraduate School Monterey, CA 93943-5000	1
4. Professor T. McNelley, Code ME/Mc Mechanical Engineering Department Naval Postgraduate School Monterey, CA 93943-5000	5
5. Professor P. Kalu, Code ME/Ka Mechanical Engineering Department Naval Postgraduate School Monterey, CA 93943-5000	1
6. Naval Engineering Curricular Officer, Code 34 Mechanical Engineering Department Naval Postgraduate School Monterey, CA 93943-5000	1
7. LT Paul D. Macri 1600 Bald Mt. Rd. Bear Creek Twp. Wilkes-Barre, PA 18702-9609	2

